Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

7 May 2019

Ref: 170108-ER-DPE-TSE- 19

Erica van den Honert Director Infrastructure Management Department of Planning and Environment GPO Box 39 SYDNEY NSW 2001

Dear Erica

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 – ER Monthly Report for April 2019 – TSE Contract and Martin Place USP

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications (MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), MOD 3_ Martin Place Metro Station (22 March 2018), MOD 5_Blues Point Acoustic Shed (2 November 2018), and MOD Administrative Changes (21 February); and
- As required by the subsequent appointment as the approved Environmental Representative (17 February 2017);

The attached summary details the key activities undertaken by Environmental Representatives for Sydney Metro – City and South West Chatswood to Sydenham during the month of **April 2019**.

Yours sincerely

Michael Woolley Environmental Representative

Cc: Sydney Metro: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam Koutsamanis, Pam Tummers, Margarita Ognjanovic, Rob Muir (JHCPBG), Jason Ambler (LL)

DPE: Kate Moore, Elizabeth Williamson, Alice Pryke

CC IEA: Larry Weiss, Julie Dickson

Summary of Contract Packages	Environmental Representative/s
Tunnel and Station Excavation (TSE)	Michael Woolley/ Alberto Paludetto
Martin Place Unsolicited Proposal USP/ISD Macquarie	Michael Woolley/Jo Robertson
Bank/Lendlease	

Key Construction Activities

TSE

Chatswood:

 Tunnelling with both TBMs and spoil handling. Intersection works on Mowbray and Hamden Road operating.

Chatswood NCW:

 Works along Frank Channon walk focussed on construction of the capping beam and retaining walls. Bland Street works included benching; soil nail installation, stockpiling and loading out spoil.

Artarmon Substation:

 Liner installed in the shaft. Few activities occurring. Preparation for handover from TSE Contractors.

Crows Nest Station:

- Ongoing excavation; wall support and profiling; nozzle construction; spoil removal off site; water treatment and various other works.
- Preparation works for "sharks fin" area.

Victoria Cross North site:

- Excavation by excavators with rock hammers and excavators with saw cutters.
- Stockpiling spoil in the shed and removal of spoil.

Victoria Cross South site:

Excavation by road header and wall support. Removal of spoil. Other support activities.

Blues Point Temporary Retrieval Site:

- Construction of frame for the remaining part of the acoustic shed and cladding installation.
- Ongoing excavation using rock hammer.
- Pile cap construction.
- Wharf access ramp in place ongoing works to complete the wharf.

Barangaroo Station:

- TBM being stored on site with assembly activities ongoing.
- Barge spoil loading activities ongoing with one to two barges sent out per day.
- Operation of water treatment plant ongoing.
- Construction of bentonite slurry treatment plants ongoing for TBM.
- Excavation; spoil management and removal offsite ongoing.
- Ongoing road header operation from the northern shaft in cross over cavern area.
- Ongoing environmental controls including street sweeper; wheel bath and water cart.

Martin Place Station- South:

- Ongoing demolition of remaining structures and removal of spoil by Delta.
- Excavation of sandstone under walkway and adjacent 50 Martin Place with 30 tonne excavator and another small excavator.
- It is understood that vibration screening criteria defined under Condition E28.1 was reached at 50 Martin Place (based on vibration monitors in the building). JHCPBG reported that works were stopped; re-assessed; modified and continued without further exceedance of the criteria.

Pitt Street North:

Excavation using road headers completed. Lining and other works ongoing.

Pitt Street South:

- Bulk demolition completed of buildings.
- Piling and capping beam works ongoing.
- Various areas cleared for heritage with NE corner still to be excavated.
- Heritage investigations ceased until remainder of slab is removed

Waterloo Station:

TBM 1 maintenance activities.

	Excavation of the station box using a crane with kibble.	
	 Hammering/cutting of side walls and wall support. 	
	 Spoil management and loading out from the northern end of the site. 	
	 Operation of the water treatment plant. 	
	 Lining of the southern nozzles and base of excavation. 	
	Marrickville precast facility	
	 Pre-cast facility operating. Storage and handling of segments outside shed and in area to north. Breaking of out of spec segments for re-cycling. 	
	Marrickville dive site:	
	 Ongoing tunnelling by TBM 2. TBM 1 broken through to Waterloo on 6 April and is traversing Waterloo Station box. Spoil management. Operation of water treatment plant. 	
MP –	 Hard demolition of 9-19 Elizabeth Street essentially complete except for basement 	
USP/ISD	adjacent Elizabeth Street.	
	 Loading of non rubble wastes into bins and load out off site. 	
	 Spread re-usable rubble across the site to form a generally even layer and create ramps between Castlereagh Street and Elizabeth Street. 	
	 Preparation and commencement of micro-piling and piling for ramp and protection of 50 	
	Martin Place.	
ER Inspectio		
TSE	Weekly inspections continued of the sites under the management of the TSE contractor. There	
IJL	were three inspections carried out during the month (no inspection was carried out after the Easter	
	break to personnel availability and Construction Industry picnic day). Actions identified during the	
	inspections comprised:	
	Waterloo – secondary containment for small fuel and chemical containers.	
	 Barangaroo – dust management, secondary containment for small fuel and chemical 	
	containers.	
	 Marrickville Dive – stormwater, erosion and sediment controls, spoil, and secondary 	
	containment of hydrocarbons and chemicals.	
	 Marrickville Pre-Cast – dust management and sediment controls. 	
	Various notes were made in the inspection reports reflecting commitments made by the TSE Contractors and risks identified during inspections. ER Inspection reports have been prepared and	
	issued to Sydney Metro and the TSE Contractor.	
MP – USP/	There was one inspection carried out in April 2019 of the demolition of 9-19 Elizabeth Street. No	
=		
ISD	new issue were identified during the inspection.	
Endorsed Do	ocument/s	
Sydney	■ n/a	
Metro	.,, .,	
TSE	Out of hours works (OOHW) approvals	
.52	MPS 33 ESR	
	Extension of time for OOHWs MPS 07 and 010	
	Martin Place OSD piling	
	Air Quality Management Plan (AQMP)	
	·	
	Construction Noise and Vibration Impact Statement (CNVIS) Chala CNVIS Roy 5 covering stackwile area.	
	Clyde CNVIS Rev 5 covering stockpile area Site Environment Plan (CER)	
	Site Environment Plan (SEP) IS NA Works Contact	
	I&M Works Carlow Street I&M Works Payer Patents Candana	
	I&M Works Royal Botanic Gardens	
	o I&M Works St Leonards Park	
	o I&M Works McLaren Street	
	 I&M Works Williams Street 	
	I&M Works Pacific Highway I&M SEP 567 Pac Hwy Crows Nest	

USP/ ISD-	Out of hours works (OOHW) approvals	
	Cat of floars works (Coffw) approvals	
Martin	OOH6 Hoarding and Tree removal	
Place	OOH6 Hoarding and Tree removal-Amended	
	Construction Environmental Management (CEMP) - Revised for micro piling	
	Construction Heritage Management Plan (CHMP) - Revised for micro piling	
•	/ Incidents / Non-compliance	
TSE	It is understood that Sydney Metro has been providing summaries of complaints to DPE	
	daily. Responses to each complaint have been noted in each complaint report, with follow up	
	actions often defined in revised reports.	
	The following non compliances related to TSE works were reported to the ER for the period:	
	 A complaint on 21 April at Victoria Cross North site was found to be related to rock 	
	hammering works out of hours and not in accordance with the approved CNVIS.	
	 A resident complained about jack hammering on Sunday 28 April which was not in 	
	accordance with the approved CNVIS.	
	JHCPBG have indicated that both incidents are being investigated and a written report will be issued	
	regarding each incident.	
USP/ ISD-	There was one complaint reported by Lend lease to have been received in relation to hoarding. This	
Martin	has been included in complaints data to DPE. There were no incidents reported by Lend Lease.	
Place		
Sydney	Complaints received for Sydney Metro works are included in complaint summaries provided to DPE	
Metro	daily.	
	There were no incidents reported by Sydney Metro for Sydney Metro conducted works as defined	
	by the project approval definition for incidents reported to DPE under condition A41.	
Audits (specific to TSE and MP ISD only)		
	d activities conducted during the period:	
■ n/a	· · · · · · · · · · · · · · · · · · ·	
Looking Forward – Core Focus Areas		
TSE	 Dust management at Barangaroo 	
	 Works in the Northern Corridor Area 	
	 Tracking of dust onto roads at key excavation sites 	
	 Heritage investigations at Pitt Street South 	
MP – USP/	Out of Hours Works	
ISD		