

A.C.N. 003 270 693

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

> 7 August 2022 Ref: 170108-ER\_DPE Jul 2022

Mr Rob Sherry Team Leader Compliance – Government Projects Department of Planning Industry and Environment Locked Bag 5022 PARRAMATTA NSW 2124

Dear Rob

#### RE: Sydney Metro City & South West – ER Monthly Reports for July 2022

A.B.N. 39 003 270 693

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15\_7400 Approval (9 January 2017) and associated modifications MOD1\_Victoria Cross and Artarmon (18 October 2017), MOD2\_Central Walk (21 December 2017), MOD4\_Sydenham Station and Metro Facility South (13 December 2017), MOD 3\_ Martin Place Metro Station (22 March 2018), MOD5\_Blues Point Acoustic Shed (2 November 2018), MOD6\_Administrative Changes (21 February 2019), MOD7\_ Administrative Changes (29 June 2020), MOD8\_Blues Point Access Site (25 November 2020), and MOD9\_Extension to Standard Construction Hours (30 June 2022); and
- Condition A26 (j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI\_8256 Approval (12 December 2018) and associated modifications MOD1\_Bankstown Station.

The attached summaries detail the key activities undertaken by Environmental Representatives for Sydney Metro – City and South West Chatswood to Sydenham for the month of **July 2022**.

Yours sincerely

Jo Robertson Environmental Representative

Cc: Sydney Metro: Carolyn Riley, Fil Cerone, Ben Armstrong, Dylan Jones, Ann Paterson, Julia Diamond, Candice Somerville AA: Available on Sydney Metro Website Contractors: Available to Contractors on Sydney Metro Website DPIE Compliance: Portal DPIE Post Approvals: Available on Sydney Metro Website

#### HBI

Healthy Buildings International Pty Ltd

1.	Central Station
2.	SSJ
3.	Line Wide (Tallawong to Bankstown)7
4.	Train Service Operation and Maintenance (TSOM) 12
5.	ISDs
6.	Barangaroo Station (BESIX Watpac)
7.	Sydenham to Bankstown Sydney Metro Corridor (SMC) and Bankstown Early Works (BEW) 32
8.	Marrickville, Canterbury & Lakemba Station Upgrades (MCL)
9.	Hurlstone Park, Belmore, and Wiley Park Station Upgrades (HBW) and Dulwich Hill Campsie and Punchbowl Station Upgrades (DCP) (Downer)
10.	Sydney Metro Retained Obligations (SM) /Other 44
11.	Statement of Limitations

# 1. Central Station

Project Approval	Contract Package	Environmental Representative/s		
SSI 7400 (C2S)	Central Station	Michael Woolley		
Key Construction Activities During the Period				
Works conducted d	uring the reporting period included:			
<ul> <li>Metro Box – Or ongoing. Instal platform edges close in the last</li> <li>Central Walk – activities. Work possession wee platforms 16-19</li> <li>Sydney Yard – S subject to capa laydown; stock</li> <li>Northern Conce the TCAC buildi</li> <li>Eastern Entrane in Randle Lane.</li> <li>Devonshire Stre</li> <li>CSR works Rail</li> </ul>	ngoing construction activities for the Chillers and Ver llation of skylight panels in Platform 14. Fit out of the s. Installation of escalators and fit out within the var t mole hole. Excavation of spoil; stormwater works in Ongoing installation of new escalators and final pane ks within hoarded work zones on suburban Platforms ekends. Excavation of spoil from some escalator acce 9. Small capacity WTP operating to treat surface waters noticy restraints there. Water pumped from the Track s piling and loading out of spoil. ourse – Ongoing works at intersection of Northern Co ing being placed on the concrete beam. ce –Ongoing fit out and general construction activitie . Stormwater works in front of building completed. eet Tunnel - In operation and used by commuters. Institute – Bitumen resurfacing of impacted areas fro - Ongoing use of the area for laydown and construct	e Platform and other levels. Various FRP works for ious levels. FRP for traffic deck including works to and around the former gasworks area. els around the new escalators. Other fit out a 16-23 and platform surface excavation during rail ess points on northern side of Central Walk for with other water largely directed to Marrickville – slabs via various tanks to the WTP. Truck access; oncourse and Metro Box area. Facia panels under es. Plans to do fit out works 24/7. Linewide works		
-	is (above ESR Platforms 24-25) - Ongoing electrical ar	nd other fit out		
	ctivities Look Ahead			
	ies as described above			
ER Inspections				
There were two ER inspections included Noise Blankets Water containe ERSED Manage	not well fixed at the Dental Hospital ed in bunded pallets ment at Sydney Yard tainment for fuels and chemicals	d on 6 <sup>th</sup> and 20 <sup>th</sup> July. Issues raised during these		
LOR were generally	responsive to closing out actions raised during inspe	ections.		



Sydney Metro has been providing summaries of complaints to DPE daily as well as to the ER.

# Leaders in Environmental Consulting

Two complaints were reported to have been received during July: one related to breakfast not being included during a respite (Alternative Accommodation) offer; the other related to closure of the bike path on Chalmers Street during stormwater works.

No Incidents were reported that would trigger reporting under Condition A41 and no non-compliant events were reported or observed by the ER.

#### Audits

There were no audits conducted during the reporting period.

#### Looking Forward – Core Focus Areas

- Water Management
- Heritage Reporting

#### 2. SSJ

Project Approval	Contract Package	EPL	Environmental Representative/s	
SSI 7400 (C2S)	Sydenham Station and Junction (SSJ)	#21147	Jo Heltborg	
Key Construction Activities During the Period				
<ul> <li>Geotechnical A</li> <li>Main Site (11 S</li> <li>Sydenham Stat handed over to</li> <li>Secondary Plaz</li> <li>Sydenham Pit a</li> <li>Way Street Lay Bankstown Add</li> <li>XPT Laydown: S</li> <li>Carrington Roa and concrete b Sydney Water)</li> <li>Bedwin Road: F including graffi</li> <li>All areas Up-tra</li> </ul>	a: TSOM site compound demobilised and in temp and Pumping Station: Formal handover to Sydney down Areas: Materials removal ongoing for trans ditional Corridor (BAC) Works Stockpiles and slurry bins removed. Site validation d Laydown: Spoil load-out to Gateway project cor arriers remained, and stabilisation required. Hand Fencing complete. Handed over to Linewide. Bedw ti removal ack of the Geotech have been removed from the J	f gate on hold du eted by TSOM. J orary use as a ca Water complete fer to JHLOR Sou complete. Hand nplete. Some m dover process to vin Road Bridge	ue to design IHLOR station works complete. PC ar park e (awaiting records) uthwest Metro Corridor (SMC) and ded over to XPT (awaiting records) aterials, including a stockpile of DGB be formalised (either to SMC_BAC or awaiting formal handover to Council,	
	nce (EPL) Premise Maps. ctivities Look Ahead			
<ul> <li>Geotechnical A</li> <li>Way Street &amp; X</li> <li>Carrington Roa SMC_BAC</li> <li>Ongoing defect</li> <li>October – diam</li> </ul>	rea: Final gate design and installation PT Laydown Areas: Preparation for formal hando d Laydown: Spoil load-out to Gateway ongoing pr	ior to handover scheduled for C	to Sydney Water, or further use for October 2022	
ER Inspections				
The following action Bedwin Road: Management P Sydenham Pit (	nspections conducted by the ER in July 2022. Ins remain open from previous ER inspections: Graffiti remains on Bedwin Road bridge; pending Plan (VAMP). Confluence Area: Graffiti remains on the Sydenha In the VAMP. Outcome pending formal handover	m Pit confluenc	e structure; pending removal in	
<ul> <li>Nil</li> </ul>				
Endorsed Documen	t/s			
	_Upcoming_Compliances_SSJ_Q1-2022 Rev01_EF	3, 12/7/2022		

Non-compliance/ Incidents or Repeat Complaints

Sydney Metro has been providing summaries of complaints to The Department of Planning and Environment (DPE) daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow-up actions often defined in revised reports. Key or repeat items of note are discussed below for SSJ.

- The ER is not aware of any non-compliances for SSJ during the period.
- There were no incidents for SSJ reported to the ER under conditions A41 of SSI 7400.
- There were no minor Class 3 environmental incidents reported to the ER during the period.
- The ER is not aware of any complaints during July 2022 that could be attributed to the SSJ works.

#### Audits

No ER involvement in audit activity including Independent Environmental Audits.

#### Summary of Environmental Performance

The scope of works conducted during the reporting period was small and low risk. The project is winding down with most project scope complete, with mainly defects remaining. The Environmental Representative (ER) is waiting on the completion of all scope and spoil load-out from laydown areas before handover and condition completion is finalised. Some laydown areas may be approved for ongoing use by SMC\_BAC, though confirmation is pending.

#### Looking Forward – Core Focus Areas

- Completion of selected Conditions of Approval and Revised Environmental Mitigation Measures
- Completion of the SSJ Compliance Tracking Report (CTR) Q2 2022.

## 3. Line Wide (Tallawong to Bankstown)

Pro	oject Approval	Contract Package	EPL	Environmental Representative
	SI 7400 (C2S)		#21423	
S	SI 8256 (S2B)	Line Wide (Tallawong to Pankstown)	ST	Swathi Gowda (North /South)
SS	I 5931 (SMTF)	Line Wide (Tallawong to Bankstown)	#12208	George Kollias (Alternate ER)
			LW	
		ctivities During the Period		
-	Construction A			
		rporating Chatswood Dive Site, Northern Connection,	Hopetoun A	ve and Valetta Lane)
Νοι	thern Connectio			
		asteners (Down Line)		
•	-	le tray installation (down track)		
	Formwork for f	irewalls soon to be ready for pour		
Blu	es Point Access	Site		
•	No works repor	ted. Early establishment for landscaping has not yet co	mmenced. N	ot inspected
SW	Corridor Tractio	on Substation sites - no works to minimal works at time	e of inspection	on
	Operation of co	mpound and laydown at Belmore Compound		
•	Dulwich Hill and	d Punchbowl TSS - No works at time of inspection		
•	Canterbury TSS	<ul> <li>Electrical fit out within TSS building</li> </ul>		
•	Campsie TSS			
	Façade inst	tallation completed		
	• Electrical fi	t out/testing and commissioning works within TSS build	ling	
	Energisatio	n of TSS scheduled for 8 Aug 22		
-	Lakemba TSS			
	• Rip- rap dra	ainage completed		
		commenced and currently paused due to gas main		
		t out within TSS buildings		
Car	iterbury to Cam	osie BPS		
•		POC) Reserve, Canterbury		
		llary Facility (MAF) - demobilised and spray grassed		
		ge site (Ausgrid side) – batters spray grassed		
-	-	int Bay worksites (Anzac St, Cooks Ave and Gould St) - r	no works at t	he time of inspection SC reports:
		g works only at Gould St (and South Parade) during Star		
		irther arrival of cables for further works to continue		
	-	ng/fault finding continuing		
Sou		ATF South Marrickville:		
•		uilding – installation of ducting on level 1		
		allation of structural steel		
		track installation and tamping completed		
	-	OHW progressing, ballast profiling, GST install and FRP 1	for footnathe	underway
-				under way
-	LIACK SIAD ALGO	<ul> <li>slab preparatory works, rail cleaning</li> </ul>		

Southern Dive:

- Services Building cladding, flashing, cable tray, ducting and solar flame (on roof) installation works
- Transformer Yard clipping down grates; Switch Rooms installing lagging, chilled water pipe

#### Surry Hills BPS works:

- Frog Hollow Reserve works completed and worksite sprayed
- Belmore St cable jointing and testing

#### Key Construction works/activities Look Ahead

Look-ahead of upcoming activities /works:

- Compliance Tracking Report (CTR) Q2 2022 CTR reporting and review process.
- Blues Point streetscaping/enhancement works during Standard Construction Hours along Blues Point Road and Henry Lawson Avenue – scheduled between Jul 2022 with completion by Q4 2022.
- Surry Hills BPS Cable jointing, testing and demobilising from Belmore St worksite to be completed by 02 Aug 22.
- Surry Hills PBS Cable pulling, jointing and testing works Randle Ln Surry Hills to complete the power supply upgrade work in Surry Hills largely during standard construction hours and some OOH works.
- Canterbury to Campsie BPS works HV cable testing and planned progressive demobilisation of worksites from 11th August, pending new HV cable arrival and associated works
- OOHW Canterbury to Campsie BPS Joint Bay dewatering works (contingency OOHW for dewatering, dependant on wet weather) – extended with anticipated completion in mid-August 2022.

#### ER Inspections

There were three ER inspections conducted by the ER in July 2022 (12/07/22, 21/07/22 and 26/07/22). Key new issues and actions raised are summarised below, with actions either closed out/ in the process of being closed out by SC:

Northern Hub and Artarmon TSS - ER Inspection #117 - 12/07/22 (Tuesday); rain 8.8mm (previous 24 hours since 9am):

No new issues raised.

#### SW Corridor Traction Substation sites. ER Inspection #118 – 21/07/22 (Tuesday)

Dulwich Hill TSS

• Material laydown area - general tidy up/removal of waste to be undertaken.

Canterbury TSS

- Construction material laydown area (Hutton St) Some loose material near skip bin to be tidied up/removed.
- Discussed site access/egress (Hutton St) and maintenance to remove some sediment accumulated around coir logs. Replacement/refreshing of geofabric near access gate recently disturbed by plant and minor maintenance to re-install section of sediment fence. Tidy-up commenced and observed during the ER Inspection.

Lakemba TSS

 Discussed housekeeping in area with SC (disposal/removal of redundant sediment fence post drainage works) and reattachment of shade cloth on ATF.

Belmore St Compound

 Site access/egress (the Boulevarde) – steel plate was observed to have shifted and some maintenance/re-installation required at access gate. Action raised for SC to address.

# Southern Dive, SMTF South, BPS works and Barangaroo Shaft: <u>ER Inspection #119 - SMTF S and BPS works (Campsie and Surry Hills) - 26/07/22 (Tuesday); Rain - previous 72 hours – 14.8mm (23/07); 3.4mm (24/07); 0.2mm (25/07)</u>

#### Surry Hills BPS Works

 Surry Hills BPS works – Frog Hollow Reserve – works completed and worksite sprayed with polymer, which was observed to be impacted by recent wet weather. Evidence of scouring observed in lower section; with sediment noted near controls established at worksite and around controls within gutter near worksite. Discussion held on-site regarding removal of sediment around controls near worksite, along gutter and additional controls to be implemented to manage ERSED risk. SC to investigate and implement further stabilisation options. Action raised for SC to address.

# Photos





Pat O' Connor Reserve - Cable Bridge Site (Ausgrid side):ABatter recently spray-grassed; some green growth observedBon batter.B

Anzac St – Joint Bay worksite (BPS works) - Anzac St Joint Bay backfilled.





**Southern Dive - Services Building:** Cladding installed on section of Services Building; with steel installed for cladding installation on exterior of building.


**Southern Dive - Fan room:** Noise dampeners pending installation in the Fan Room.





Leaders in Environmental Consulting

HBI



Leaders in Environmental Consulting

Dive structure within acoustic shed: Image shows dive Northern Connection: Formwork in place for pour of fire structure view from within acoustic shed walls in tunnel **Endorsed Document/s** CTR Q1 2022 Rev C Final Consistency Assessment - Blues Point Restoration and Streetscaping - Ver 3 OOHW-215 - Campsie BPS Joint Bay Dewatering - Rev 07 OOHW-216 - Campsie BPS Traffic Control and Joint Bay Dewatering on South Parade – Rev 04 OOHW-228 - Dulwich Hill TSS - Building Delivery and Civil Works July 2022 - Rev 01 OOHW-226 - Surry Hills BPS Belmore Street Joint Bay Rev 02 OOHW-233 - Dulwich Hill TSS Crane Lifts and Civil Works WE07-WE08 OOHW-234 - Punchbowl and Lakemba TSS CSR WE07-WE08\p Non-compliance/ Incidents or Repeat Complaints Sydney Metro has been providing summaries of complaints to DPIE daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow up actions often defined in revised reports. Key or repeat items of note are discussed below for the respective projects. No non-compliances reported to the ER in this reporting period. There were no incidents for Line Wide reported to the ER under conditions A41 to A44 of SSI 7400 or A36 of SSI 8256. One minor incident (Class 3 events) reported to the ER, for this reporting period refer below: 08/07/22 - Dulwich Hill TSS (Class 3): While being driven to the collection point in the site driveway, an EWP developed a minor hydraulic oil leak (<5 L) onto a sealed road surface. EWP stopped and spill kit deployed. Leak contained on the road surface and cleaned up. Complaints during this reporting period are summarised below: 15/07/22 - Marrickville Dive Site and SMTFS - Worker behaviour - allegation is that complainant was catcalled by two workers who appeared to leave the SMTF South Site. Minimal detail from complainant to confirm if workers were from SMTF South site. 15/07/22 - Surry Hills power upgrade - Notification of work; Transport & Parking; Worker behaviour - complainant expressed concerns regarding the on-going works on Belmore St, that parking has been difficult for residents due to works and questioned the work methodology. Resident stated he had received no communication from SM with regards to updates with the on-going works. 22/07/22 - Surry Hills power upgrade (LWW) - Notification of work, Traffic, Transport & Parking - Resident responded to the weekly email sent out by SC Stakeholder Manager, expressing concerns regarding the on-going works on Belmore Street and that due to the works, parking has been difficult for residents. For above Surry Hills complaints - SC's close out response to complainants included explanation that due to unplanned wet weather, delays in works have resulted to ensure the cables and ground is dry enough to undertake works. 27/07/22 - Blues Point - noise and vibration (Std Hours), respite and AA - complain about the on-going loud hammering noise emanating from works at Blues Point. Resident stated that the issue caused major disturbance and was unable to sleep as he is a paramedic doctor working irregular shifts. He was also not happy that no AA was offered or respite from the works. He requested for more information regarding the works, duration and when the works will conclude. . 27/07/22 – Blues Point – access - Resident sent a follow up email after initial enquiry into beach access being reinstated at Blues Point. Complaints during this reporting period unrelated to SM activities: 21/07/22 - Chatswood Dive site (two complaints) - Noise and vibration OOHW; Notification of work (not related to Sydney Metro) - Residents emailed about (loud) noise coming from the rail corridor. SC Stakeholder Manager confirmed and emailed the residents advising the works in the area were not related to SC and provided the relevant information about known Sydney Trains works in the area. Audits Nil this reporting period **ER Closing Comments and Looking Forward** No Line wide related complaints from the mid-year shutdown possession between 2-14 July 2022 (Southwest Corridor works). . No OOHW noise complaints in July. Two complaints noted for Surry Hills BPS works (Belmore St worksite) in July regarding ongoing works, work update and parking difficulties at Belmore St. Works are scheduled to be completed

including demobilisation from the Belmore St worksite by 02 Aug 22.

- Current works at LWW sites continue to be managed appropriately; ER Inspections across this month continued to identify generally minor actions and improvements.
- Overall, the Project performed well in the reporting period. The Project Team continue to be responsive to queries/comments raised in document reviews and recommendations made by the ER.

#### Looking forward:

- Blues Point streetscaping/enhancement works during Standard Construction Hours along Blues Point Road and Henry Lawson Avenue – scheduled between Jul 2022 with completion by Q4 2022.
- Cable pulling, jointing and testing works Randle Ln Surry Hills to complete the power supply upgrade work in Surry Hills largely during standard construction hours and some OOH works.
- Canterbury to Campsie BPS works HV cable testing and planned progressive demobilisation of worksites from 11 August, pending new HV cable arrival and associated works.
- OOHW Canterbury to Campsie BPS Joint Bay dewatering works (contingency OOHW for dewatering, dependant on wet weather) – extended with anticipated completion in mid-August 2022. As per the ER's OOHWA condition, SC is required to provide a weekly progress report of any OOHW for dewatering. To date SC has reported no OOHW undertaken for dewatering. Continue to monitor actual OOHWs undertaken in August through weekly progress report updates from SC to the ER.

# 4. Train Service Operation and Maintenance (TSOM)

SSI 7400 (C2S) SSI 8256 (S2B) SSI 5931 (SMTF Key Constructio	Train Service Operation and Maintenance (TSOM) Activities During the Period (July 22)	Swathi Gowda (North /South) George Kollias (Alternate ER)		
SSI 5931 (SMTF				
Key Constructio	Activities During the Period (July 22)			
	: Dynamic train testing between SMTF North and Chat			
	: Cable tray, cables and cabinet installation in Administ	-		
	ubstations: Installation of radio mast at Campsie and P			
	corridor: Inspections (Aug 2022 - TBC pending industria			
	rridor: Cable pulling and termination at Chatswood Sta	ation		
	Ibstation: Testing and commissioning			
	going installation of cables and trackside equipment in	tunnels, Cross Passages (XPs) and 5G Installation		
<u>Stations</u>				
<ul> <li>Central, Wai installation</li> </ul>	erloo, Martin Place and Victoria Cross: Platform Screen	Doors (PSD), communications equipment and cable		
Sydenham:	PEB installation, finishing work; testing and commissior	ning of communications equipment ongoing.		
Crows Nest:	Cable containment, equipment/cabinet installation an	d cabling. Inspections of equipment rooms.		
<ul> <li>Barangaroo</li> </ul>				
<ul> <li>Pitt Street: I</li> </ul>	nstallation of PSDs, cables and fit out of communicatio	ns rooms.		
<b>Key Constructio</b>	n Activities Look Ahead – August 2022			
SMTF-North	: Dynamic train testing between SMTF North and Chat	swood		
SMTF-South	: Cable tray, cables and cabinet installation in Administ	ration Building		
Southwest \$	ubstations: Installation of radio mast at Campsie and	Bankstown Substations		
Southwest	Corridor:			
o Ins	pections and survey			
o Ins	allation of signalling equipment between Sydenham a	nd Punchbowl		
Northern Co	rridor: Cable pulling and termination at Chatswood Sta	ation (days and nights – 6 to 8 August)		
<ul> <li>Tunnels: Ongoing installation of cables and trackside equipment in tunnels, XPs and 5G Installation</li> </ul>				
<u>Stations</u>				
Central, Waterloo, Martin Place, Victoria Cross, Crows Nest, Pitt Street and Barangaroo: Installation of PSDs,				
communications and signalling equipment and cables				
<ul> <li>Sydenham: PEB defect work. Testing and commissioning of PEBs and communications equipment.</li> </ul>				
ER Inspections				
<ul> <li>No ER inspe</li> </ul>	tions conducted in July.			
Photos				

■ N/A
Endorsed Document/s
<ul> <li>Nil</li> </ul>
Non-compliance/ Incidents or Repeat Complaints
Sydney Metro has been providing summaries of complaints to DPIE daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow up actions often defined in revised reports. Key or repeat items of note are discussed below for the respective projects.  The ER is not aware of any complaints or non-compliances. There were no incidents for TSOM reported to the ER
under conditions A41 to A44 of SSI 7400 or A36 of SSI 8256.
Audits
<ul> <li>No audits proposed</li> </ul>
Looking Forward – Core Focus Areas
Nil

# 5. ISDs

Project Approval	Contract Package	Environmental Representative/s		
	Martin Place ISD Macquarie Bank/Lend Lease	Michael Woolley / Rui Henriques		
	Victoria Cross ISD (VC-ISD) - Lend Lease	Swathi Gowda / Michael Woolley		
SSI 7400 (C2S)				
(Does not include	Crows Nest ISD – AW Edwards	Rui Henriques / George Kollias		
associated SSDs)	Pitt Street ISD – CPB Contractors	Rui Henriques / Michael Woolley		
	Waterloo ISD – John Holland	Swathi Gowda/Jo Robertson		
-	ctivities During the Period			
MP-ISD				
Bligh Street:				
	eries and pumping. Various other deliveries.			
	tion of the Water Treatment Plant (WTP) and discharge of wa	ter to stormwater.		
Martin Place South				
	ruction (FRP) of walls; columns, beams and floor slabs up to st			
	b in Martin Place that will form the pedestrian way of Martin	Place.		
_	construction activities. parding works (OOHWs).			
Martin Place North				
	g work activities ongoing such as FRP for columns; lift shafts;	walls: floor slabs and other various items		
	well above street level (to level 12).			
	ress and egress off Elizabeth Street with footpath moved into	the site area.		
Station Caverns an				
Installation of	ventilation/exhaust systems			
	ctivities including installation of panelling, services and fire saf	fety systems.		
	ks in the station caverns – separated from Lend Lease activitie			
VC-ISD (update fro	m Contractor)			
<b>Construction Activ</b>	ities:			
North:				
<ul> <li>Hoarding work</li> </ul>	S			
	ks within shaft, concrete pours/steel fixing/formwork			
<ul> <li>Deliveries</li> </ul>				
Cavern:				
-	led over to Line Wide			
	GRC panels installation			
• Station fit-out				
South:	ation clobe concrete neuro stael fining and famming			
<ul> <li>Carpark slab/st</li> <li>Station jumpfo</li> </ul>	ation slabs concrete pours, steel fixing and formwork			
<ul> <li>Station jumplo</li> <li>Jumpform pou</li> </ul>				
<ul> <li>Jumpform pou</li> <li>Waterproofing</li> </ul>				
<ul> <li>Waterproofing</li> <li>Blockwork</li> </ul>				
CN-ISD				
	(patch works), steel fixing and shuttering (Sites A - C)			
	ping and pouring (Level 0 pours commenced)			
conciete pulli				
<ul> <li>B4 OTE and fit</li> </ul>				
<ul> <li>Services, finish</li> </ul>	es, and fit out of B5 platform, B4 OTE, B3 plant room.			
<ul><li>Services, finish</li><li>Line Wide fit o</li></ul>	es, and fit out of B5 platform, B4 OTE, B3 plant room. ut works on B6 (Platform)			
<ul><li>Services, finish</li><li>Line Wide fit o</li><li>Dewatering the</li></ul>	es, and fit out of B5 platform, B4 OTE, B3 plant room. ut works on B6 (Platform) e surface water from the site due to heavy rain			
<ul> <li>Services, finish</li> <li>Line Wide fit o</li> <li>Dewatering the</li> <li>Clearing mater</li> </ul>	es, and fit out of B5 platform, B4 OTE, B3 plant room. ut works on B6 (Platform)			

HBI

Healthy Buildings International Pty Ltd

## PS-ISD

#### Pitt Street North

- Level 2 FRP ongoing, close to completion
- Capping beam demolition along Park Street ongoing.
- FRP for Level 3 started from the east and west to the centre
- OSD high-rise core establishment
- Level 04 FRP
- Level 01 complete
- Over Station Development (OSD) Central Core (kicker) wall reinforcement installation and concrete pours in progress from L02-L03.
- Speed Panels (All Basement Levels)
- Utilities investigations in surrounding streets nearing completion

#### Pitt Street South

- Main jump cycle progressed to Cycle 16 & 17 (Level 6)
- Level 04 & 05 FRP
- Precast Façade Panels Level 03 05
- Perimeter Scaffolds Princeton Apartments, The Edinburgh Castle, FRNSW, Pitt Street & Bathurst Street
- B1 Blockwork
- Speed Panels (All Basement Levels)
- Mechanical, Electrical and Plumbing to B4 00
- Partitions & Ceilings B4 00
- B2 Critical Equipment Deliveries: Mechanical Switchboards, LV Switchboards & HV Switchgear
- Utilities investigations in surrounding streets nearing completion

#### Adits and Platform Caverns

- GRC (lower internal cladding) panel installation ongoing.
- Installing cladding subframes above GRC panels
- Platform Screen door cladding
- Platform Screen door cladding
- Services containments install to platforms
- Ceiling cladding/ light tubes installation

#### WL-ISD (update from Contractor)

- Utilities works ongoing for HV/LV & Sydney Water scope
- Ausgrid outage 3 works ongoing
- Cranage works from Cope Street South and internal site ongoing
- General deliveries ongoing
- FRP conducted at surface level, level 1 and 2
- Block work install and fill occurring across B3 and at surface level
- Fit out works and service installation across B5 ongoing and beginning at B3 South and concourse level
- Electrical cable pulling in the station
- Transformer delivery, Level 1 and 2 24 hours pours upcoming
- Earthing pit underway on Cope Street
- Capping beam removal:
  - portion of Western part removed through hammering.
- Southern side has partially been cut

#### Key Construction/Activities Look Ahead

#### MP-ISD

- Activities as described above ongoing.
- OOHWs relating to utilities and hoarding and other construction activities.
- Planned removal of the temporary pedestrian bridge with pedestrians to walk over the MPS site.

#### VC-ISD

- CTR Q2 2022 review/reporting
- Victoria Cross South site Ongoing OOH (evening & weekend) July September 2022
- Victoria Cross North site Ongoing OOH works (evening/ weekend day OOH) extended for August September 2022

#### CN-ISD

- Steel fixing and shuttering (Sites A C).
- B4 OTE cladding and fit out
- B2 slab FRP and concrete pours
- B2 to B1 and ground Perimeter walls FRP and concrete pours
- Girder deliveries for B1/Level 0
- B1 FRP
- Concrete pumping and pouring from Pacific Highway and Clark Lane North and South
- Services, finishes, and fit out of B5 (platform), B4 OTE, B3 and B4 plant rooms.
- Blockwork to rooms within Level B3
- Interface- Line Wide works on B6 (below Platform)
- Demolition of Hume Street Bridge

#### PS-ISD

#### Pitt Street North

- OSD Central Core Wall reinforcement installation continued
- L05 FRP
- Shotcreting on Eastern boundary
- B1, 00 (Ground Floor) & 01 Blockwork
- Concrete Floor on level 3 and 4.
- Utilities installation in surrounding streets

#### Pitt Street South

- Main jump cycle progressed to Cycle 18
- Level 05 & 06 FRP
- Precast Façade Panels Level 03 06
- Perimeter Scaffolds Princeton Apartments, The Edinburgh Castle, FRNSW, Pitt Street & Bathurst Street
- B1, 00 & 01 Blockwork
- Speed Panels (All Basement Levels)
- MEP (Mechanical Electrical Power) B4 00
- Partitions & Ceilings B4 00
- Escalator Cladding Structural Steel
- Utilities installation in surrounding streets

#### Adits and Platform Caverns

- GRC install to South Adits
- PSD cladding to West Platform
- Site accommodation dismantle at South Adit
- Aluminium ceiling tube subframes install to East Platform
- Services containments install to East & West Platforms
- PSD door subframe install to East Platform
- Installation of Insulation on the ceiling.

#### WL-ISD

- CTR Q1 2022 review/reporting
- Ongoing utility works ongoing in local roads around site, including OOH
- Capping beam removal continuing including Wire Saw methodology investigations during standard hours
- Ground Level, Level 1 and Level 2 concreting works, including OOH

Inspections
-ISD
ere was one ER inspection conducted by the ER in July on 29 <sup>th</sup> July. During the inspection no issues were raised. Site ivities are very repetitive and building related works rather than civil works.
ISD
e ER inspection was conducted by the (Alternate) ER on 12 July 2022 (Tuesday) (ER inspections are on a three weekly
le weather permitting).
One new observation raised by ER on condition of fig tree (VCN -McLaren St); contractor showed and provided a copy
of the arborist report to the ER.
-ISD
ere were two ER inspections on 13 July 2022 and 27 July 2022 respectively (ER inspections are on a fortnightly cycle ather and health permitting). Both inspections were conducted by the ER. The following issues were raised: AWE to monitor spill mitigation measures implemented during concrete deliveries and pumping through static line. AWE to implement measures to encourage storage of flammable liquid containers in appropriate stores immediately after use. AWE to ensure concrete washout collection basins are covered prior to rain and emptied in a timely manner Hume Street bridge demolition delayed due to inclement weather and being cleared in preparation for demolition starting 1 August. AWE outlined that utilities installation in public domain areas on Clarke St as currently designed would require removal of all trees on Clarke St between Hume St and Oxley St. As the SDPPD states that no trees will be removed the SDPP will require amendment and DPE approval or the design requires modification. Sydney metro to make enquiries with Sydney Metro design team and rectify issue.
ISD
ere was one ER inspection on 12 July 2022 (ER inspections are on a three weekly cycle weather and COVID permitting).
ere were no issues raised during the inspection.
-ISD
e ER inspection was conducted by the ER on 21 July 2022 (Thursday) limited to external areas of WL ISD due to rain inspections are on a three weekly cycle weather permitting). Rain (mm) recorded prior to inspection day – 11.6mm and mm on 20 July 2022 and 19 July 2022. The following new issues were raised: Cope St compound - JHG to investigate and either install concrete barrier or extend noise blanket to address a gap identified in ATF. Cope St compound - Jerry cans noted without secondary containment to be removed/stored appropriately. Botany Rd (near Wellington St end) - minor graffiti noted on site hoarding to be addressed in accordance with Project

# Photos





Martin Place North – from Castlereagh Street north of Hunter Street





Martin Place North – Works well above Level 12 (above the SSI level).



Martin Place– existing pedestrian footpath to be removed, in coming months, closing entrance to the Commonwealth Bank. Caverns- ongoing fit out works.




Martin Place – Construction of new slab where pedestrians will be directed to once bridge is closed.




Martin Place South – FRP works ongoing

Leaders in Environmental Consulting




**Victoria Cross North Shaft**: Core jumpform noted above ground level and concreting works in progress for slab (1 floor).



Victoria Cross North Yard Area: Observation of noise blankets in place around concrete pump lines (good practice)




Victoria Cross South (VCS): Jump form at VCS. Steel fixing and concrete pours occurring at Level B3



Station Cavern: GRC panel installation /station fit out

HBI Healthy Buildings International Pty Ltd









underway.

PSS B1 internal walls painted with HVAC penetrations

Leaders in Environmental Consulting

HBI Healthy Buildings International Pty Ltd





HBI

Healthy Buildings International Pty Ltd

Complaints / Incidents / Non-compliance	
<ul> <li>ALL</li> </ul>	
Sydney Metro has been providing summaries of complaints to DPE daily and a summary to the ER. Responses to complaints have been noted in each complaint report, with follow up actions often defined in revised reports. Compare discussed where relevant for each package below. There were no incidents for any of the ISDs reported to the ER under conditions A41 to A44 of SSI 7400. Where the aware of minor events and non-compliances, these are as documented below.	
MP-ISD	
There were no complaints reported to have been received by Lendlease during the reporting period. Nil incidents u	inder
the MCoA or non-compliances were reported to or observed by the ER during this reporting period.	
VC-ISD	in a th a
<ul> <li>Nil incidents or non-compliances reported to the ER during this reporting period. One Project related complaint dur reporting period is summarised below:         <ul> <li>28/07/22 - CSW - Victoria Cross Station (ISD) - Noise &amp; Vibration – OOHW - Complaint received about works at North site at approximately 9:30pm earlier that night. Noise on site was described as metal-on-metal banging a less concerning noise of sawing. Complainant stated that there were flood lights on site, but all (works) finished about 9:40/9:50pm. OOHW had been notified and further investigation of noise data was undertaken to identified to the distribution list and has provided details to be added to the distribution list.</li> </ul> </li> </ul>	the and a d at fy any
<ul> <li>Complaints unrelated to SM activities for reporting period:</li> <li>11/07/22 - Noise &amp; Vibration – OOHW - stakeholder complained regarding a large amount of noise coming from on Berry Street, North Sydney. Further investigations found that Victoria Cross South site had no works happen time of the complaint. Works deemed unrelated to VC ISD/Sydney Metro activities.</li> </ul>	
CN-ISD	
There were no non-compliances/incidents identified by the ER this period:	
<ul> <li>There was one complaint during the period, relating to noise:</li> <li>20 July - Stakeholder called at 23:20 regarding excessive noise in close proximity to callers' property (Pacific Hig On investigation work had wrapped up on site at 9pm due to rain, and from review of time lapse video it was identified that the work was not related to the site. Stakeholder was contacted immediate after the initial call r and again the following day to explain this and that it was likely Council or a utility provider conducting works.</li> </ul>	
PS-ISD	
There were no non-compliances/incident reported to the ER this period. There were nine (9) complaints during the period, seven (7) relating to noise, one (1) relating to access, and one (1) relating to dust and debris. Of the nine (9) complaints seven (7) were related to the sites the others are thought to r to nearby construction by others.	
<ul> <li>17 July - Resident emailed to complain about noise generated from work on Pitt Street by Australian Utilities</li> </ul>	
Management. CPM explained that utility investigation works are in the road and footpath and road occupancy licenses only allow works on the road from 8pm. As part of our approvals, high noise activities (such as jackham and saw-cutting) are to be completed before midnight. CPB asked whether the resident receives weekly email updates, as these emails specify when utility investigation work will take place in the road/footpath. The reside confirmed that he does receive these emails and will read over it to check when utility investigations are taking Thanked CPM for the details and information.	ent
<ul> <li>17 July - Resident sent through an email regarding ongoing work for the Pitt Street Station project and music pl on site. The resident also expressed frustration about government projects and excuses used to extend constru- hours e.g., COVID, social distancing, expedited infrastructure to boost the economy. CPM has raised the issue o to the internal team. Even though the music wasn't played for long on site, they will need to address this with t team and reiterate that no radios/speakers are to be on site.</li> </ul>	iction of music
18 July - Shift Manager at Kimpton Margot Sydney approached Site Supervisor to advise that she has received r complaints from customers. CPM met with representatives at Kimpton Margot during a doorknock and discuss recent complaints. The Kimpton Margot representatives advised that their major concerns regarding noise is fructure idling. CPM spoke with representative at Kimpton Margot to provide update on truck idling complaint. A that we have contacted Bingo Industries to reiterate their site requirements of not idling in the street. They have passed this information on to their operations team, and this will be delivered to their drivers. The night shift supervisors will also toolbox any drivers visiting site to reiterate that there should be no idling in the street. CPN	ed the om dvised ve

movement, reach and swing radius, we cannot move deliveries to Bathurst Street. The tower crane has more movement over Pitt Street. The Kimpton Margot Sydney representative thanked the CPM for the information.

- 18 June Resident enquiry about construction hours and complaint about construction noise and hum/vibration. Provided the resident with details on utility investigation work that was taking place last night around the Pitt Street South site. From the site diary, high noise activities including jackhammering and saw-cutting were completed before 9pm, vacuum truck (which may be the source of the hum/vibration) was completed at 10pm, and the team were offsite by 1:30am. Provided the resident with clarification on extended work hours and how the community are notified prior to any work commencing. Provided the resident with the two July 2022 notifications (OOH and overarching) and asked whether he would like to be added to the weekly email distribution list. CPB provided the resident with her direct mobile number if he would like to discuss any details further. The resident confirmed that the noise was from the road/footpath and appreciated the detail provided by CPB.
- 19 July 23:47 Resident at Princeton Apartments advised of jackhammering work in Pitt Street (near the Pitt Street South site). He received a notice advising that work would be low noise tonight. Upon investigation CPM advised the resident that she is not sure who was working in the area. The Site Supervisor mentioned he saw Ausgrid and Retro Traffic vehicles in Bathurst Street early in the night, however did not see them setting up. The resident appreciated the update and investigation. Advised CPM that there is a road plate on the road, so they most likely will return. Will inform the strata committee that it was not associated with Sydney Metro work. CPM will speak with the site night shift supervisor to keep an eye out for any contractors working in the road.
- 20 July 9:27 Resident from Princeton Apartments complaining about jackhammering work last night. Details were
  provided to the customer via email, informing him that the jackhammering work was not related to Sydney Metro
  work. CPM advised that she would speak with the Site Supervisor to keep an eye out for any contractors working on
  surrounding roads/footpaths.
- 22 July Building Manager at Eurotower advised of a noise complaint from resident. CPB project representatives (construction lead and environment) have determined from video footage the beeping noise to be actually a quacker from an Elevated Work Platform (EWP). The team have consulted with the Safety lead who has advised of this requirement on EWP's. CPM provided Building Manager with details from investigation, including reason for the beeping noise recorded in the video, noise levels remaining compliant, use of hand tools and noise from metal material. Issues raised by the resident will also be communicated with the construction team to ensure noise is being minimised where possible.
- 30 July Pitt Street North Cafe owner complained that he did not receive notice about the footpath closure for reinstatement and people cannot access his café. CPM confirmed that access was still provided to the cafe, the footpath was closed from the boundary of the cafe and the Sydney Metro site.

The cafe owner was annoyed that pedestrians could not cross Castlereagh Street from the opposite side to his cafe. He mentioned that the fences in front of his shop stopped people from getting to his cafe. If he knew about this work he would've closed the shop. CPM advised that the pedestrian barriers are a safety requirement so no one goes into the traffic lane closure/work area.

CPM advised that this work was communicated in the weekly email sent on Friday 22 July. Another email was sent advising directly impacted properties along Castlereagh Street of the temporary lane closures. She will confirm with him if they need to work again tomorrow. CPM appreciated that sometimes emails are missed, so moving forward, she will visit the cafe to speak with the owner if we need to close the footpath around their site. CPM also confirmed that work would be taking place tomorrow to pour concrete for the driveway. Cafe owner appreciated the update and that the CPM will visit him moving forward.

30 July – Members from Fire and Rescue NSW - Bathurst Street team spoke with the Site Supervisor about dust and debris from site in their outdoor area. The Site Supervisor visited the Fire and Rescue NSW - Bathurst Street and observed dust and construction debris on the ground and tables in their outside area next to the Sydney Metro site. Construction workers were sent into the property to vacuum the dust, clean the tables and mop inside. The Site Supervisor immediately stopped any work on site that could possibly cause the dust. CPB Senior Project Engineer and Community Place Manager will speak with the Senior Representative at Fire and Rescue NSW to discuss controls and monitoring that can be implemented to eliminate the issue.

#### WL-ISD

One minor (Class 3) incident and no non-compliances reported to the ER during this reporting period. Summary of minor incident provided below:

- 30/07/22 Class 3 WL ISD During night shift operation a minor oil leak was observed from the manitou (less than 5L) on-site (hardstand). Spill kit material used to absorb oil leak.
- Complaints during reporting period are summarised below:
- 11/07/2022 WL ISD Noise & Vibration OOHW Stakeholder complaining about noise from utility work on Wellington Street. AA was offered but not accepted by stakeholder.
- 27/07/2022- WL ISD Noise & Vibration OOHW Stakeholder complaining that the there was a hammering noise on Monday and Tuesday nights, at approximately 2am which goes on for 20-30 minutes. CPM advised that all works at the time of the noise experienced were within approved noise and vibration levels and offered the stakeholder customised earplugs. Stakeholder emailed on 28/07/2022 to report that the noise had stopped and to take up the offer of earplugs.
- 28/07/2022- WL ISD Noise & Vibration OOHW/worker behaviour Resident called to complain about music coming from the site at night. S&CLM notified site supervisor straight away and music switched off. Correspondence to subcontractor to be issued regarding music. Site toolbox to be completed with all nightshift staff. S&CLM apologised to the resident and offered ear moulds which were accepted.
- Complaints unrelated to SM activities during reporting period:

Nil

#### Audits (specific to packages reported in this report)

No ER involvement in audit activity including Independent Environmental Audits.

Looking Forward – Core Focus Areas and ER Closing Comments

#### MP-ISD

#### Nil

VC-ISD

#### **Core Focus Areas**

- Continue to review/monitor OOHWs planned and approved:
- Victoria Cross South site Ongoing OOH (evening & weekend) July September 2022
- Victoria Cross North site Ongoing OOH works (evening/ weekend day OOH) extended for August September 2022
- Continue to review OOHW noise monitoring including any new modelled scenarios in OOHWAs, any associated complaints and issues.

#### **ER Closing Comments:**

Complaints and more specifically OOH noise complaints have reduced in reporting period with 1 x OOH project related noise complaint received in July 2022 (related to the Northern site), with resident added to distribution list for notifications following investigation.

The Project has performed generally well throughout the period and continues to be responsive to queries/comments raised in document reviews and any recommendations made by the ER/AA.

#### CN-ISD

#### **Core Focus Areas**

Significant out of hours planned to continue with girder deliveries continuing in the upcoming period.

#### **ER Closing Comments:**

Project has performed generally well throughout the period with continued greater effort and collaboration in relation to community consultation and engagement. Complaints generally and noise complaints specifically reduced considerably.

#### PS-ISD

#### **Core Focus Areas**

Out of hours planned to continue, including utilities installation in surrounding streets.

#### **ER Closing Comments:**

Project has performed well throughout the period, however frequency of complaints related to project increased slightly as a result of utilities investigation works and generally increased activity in public domain areas. To address this, the project has increased their community engagement efforts in terms of general face to face interaction. Effectiveness, will be monitored in upcoming periods.

HBI

#### Healthy Buildings International Pty Ltd

# WL-ISD

#### **Core Focus Areas**

- Continue to review/monitor OOHWs planned and approved.
- Continue to review/monitor complaint numbers and issues.

#### ER Closing Comments:

- Three complaints relating to OOH noise including worker behaviour (latter an avoidable complaint) noted for the reporting period; relative to amount of works being approved and undertaken in accordance with the OOHW Protocol. Contractor's Community and Stakeholder Manager continued providing complaint details/follow-up and close- out to ER and AA.
- First Community Engagement Drop-in Session held by the Project on 21 July 2022 providing the community an opportunity to drop in and ask questions. Project plans to hold these sessions on a quarterly basis.
- Project has performed generally well throughout the period and has been responsive to queries/comments raised in document reviews and any recommendations made by the ER/AA.

# 6. Barangaroo Station (BESIX Watpac)

Project Approval	Contract Package	EPL	Environmental Representative/s
SSI 7400 (C2S)	Barangaroo Station (BESIX Watpac)	N/A	Jo Heltborg
Key Construction A	ctivities During the Period		
Civil:			
	lickson Road bridge deck and vibration moni	-	-
	orks, including sheet piling, trenching, pipe in	stallation and back	fill
<ul> <li>Dewatering of</li> </ul>			
	o Hickson Road temporary alignment operati	ional	
	ridge deck demolition commenced		
	500T crane to commence removal of steel b	oridge girders at nig	ht
	tion and backfill of the shark's fin		
	mported tunnel spoil from Rozelle Interchang		
	management of asbestos and coal tar conta	minated spoil	
	nt Plant (WTP) operation.		
Station Box:			
-	ural steel, scaffolding, concrete and blockwo	ork	
<ul> <li>Continue lift in:</li> </ul>			
<ul> <li>FRP works to st</li> </ul>			
	<pre>ictwork installation (electrical, fire, hydraulic</pre>	s)	
<ul> <li>Sandstone faca</li> </ul>			
	s with Linewide.		
-	ctivities Look Ahead		
	f sheet piling and excavation for stormwater	trunk relocation	
	f backfilling of the shark's fin		
	olition of the Hickson Road bridge deck, and		al at night
	services installation to continue in the statio	n box	
	works - doors, painting services rooms etc		
	Headland Park Car Park works		
<ul> <li>Trenching and</li> </ul>	tree removal at Nawi Cove for the seawater of	cooling system wor	ks.
ER Inspections			
There were two ins	pections conducted by the ER in July 2022 (2	14 <sup>th</sup> & 21 <sup>st</sup> July). Iss	sues raised during the inspection (and i
general over the mo	onth of July) were as follows:		
<ul> <li>Potential Non-or</li> </ul>	compliance with CoA E107 and environmenta	al incident resulting	g from the uncontrolled release of wate
into Nawi Cov	e on 13/7/22 during trench dewatering. V	Vater quality mon	itoring conducted after the event wa
inadequate. Po	tential pollution incident and legislative non-	-compliance with s	120 POEO Act; EPA interest.
<ul> <li>A worker was o</li> </ul>	bserved to be shovelling sludge from the bur	nd under the WTP c	onto the adjacent internal haul road. Th
material is pote	entially contaminated and should be classific	ed and disposed of	fsite in accordance with the EPA Wast
Classification G	uidelines and the POEO Waste Regulation 20	014. This activity is	a potential Non-compliance with REMN
WM1 "All was	ste would be assessed, classified, manage	d and disposed o	f in accordance with the NSW Wast
	uidelines'. The contractor will raise the NC in		
	t of topsoil and vegetation was observed in a	-	entre of the site. This material should b
	and be classified prior to offsite removal in a		
	he Hickson Road bridge deck and vibration m		
	the Hickson Road bridge deck and noise as		
mitigation.			
Stockpiling of h	azardous waste impacted with coal tar and a	ashestos remediati	on approach Application of appropriat

- Stockpiling of hazardous waste impacted with coal tar and asbestos, remediation approach. Application of appropriate controls.
- Stockpile management, including ERSED controls and dust reduction measures for tunnelling spoil.
- Redesign and water management/discharge plan for the western civil pit; update to CEMP & Sub-plans; DPE submission.



Hickson Road temporary road realignment and demolition of the old Hickson Road bridge deck



Stockpiles of hazardous waste

Rozelle tunnelling spoil



WTP bund water and sludge being emptied onto the haul road (NC with REMM WM1)

Nawi Cove foreshore after spill clean-up (incident 13/7/22)

# Leaders in Environmental Consulting

HBI Healthy Buildings International Pty Ltd



Trench from which dewatering occurred during incident on 13/7/22

WTP bund that overflowed during incident on 13/7/22

#### **Endorsed Document/s**

- OOHWA-008 July 2022 Traffic Switch Hickson Road Rev02, 1/7/2022
- Environmental Requirements Completion Form BS Q4\_2021\_ER, 15/7/2022
- OOHWA-009 Steel Beam Removal at Night, Hickson Road Rev02, 22/7/2022
- OOHWA-009 Steel Beam Removal at Night, Hickson Road Rev03, 26/7/2022

#### Non-compliance/ Incidents or Repeat Complaints

Sydney Metro has been providing summaries of complaints to DPE daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow-up actions often defined in revised reports. Key or repeat items of note are discussed below for Barangaroo Station.

There were no incidents for Barangaroo Station reported to the ER under condition A41 of SSI 7400 for the period. A potential Class 2 incident reported to DPE on 13/7/22 (uncontrolled release of muddy water to Nawi Cove) was classified as Class 3 after an investigation found it was unlikely that material environmental harm was caused.

**13/7/2022:** A trench was being dewatered into the bund under the Water Treatment Plant, when the hose broke loose and discharged muddy water under the site hoarding, across the footpath and into the harbour at Nawi Cove (both directly and via the stormwater network). Notifications were made to Sydney Metro, the ER, NSW EPA and DPE in accordance with CoA A41. The methodology for pumping into the bund of the WTP will be addressed and a method of ensuring that the hose does not become dislodged again established. Whilst a methodology to secure the pump flat line to the bund is developed all pumping will be done with supervision of the pump line discharge to the bund. A toolbox talk will be conducted by WARD Civil and BESIX Watpac to communicate this to the work group. In the future, laboratory sampling containers will be kept in the BESIX Watpac site office. The BESIX Watpac Environment Manager, Environmental Coordinator, or a suitably trained delegate will take water samples in the event of a future incident. BESIX Watpac has also committed to keeping a portable water quality monitoring kit on site to measure TSS and pH on request. Further, WSP have been engaged to undertake an environmental impact assessment. It should be noted though that the this was still under investigation at the time of writing this report.

The ER is aware of one complaint received during July 2022 related to BESIX Watpac works:

29/7/2022 (reported 1/8/2022): Complaint regarding sleep disturbance and awakening to noise at 1am. Approved out
of hours work (OOHW) were being undertaken at the time (OOHWA-009) for Hickson Road steel beam removal via 500T
crane. The resident also complained about dust and vibration during daytime work. The complaint is under investigation
by BESIX Watpac, the Comms Team and the Acoustics Advisor (AA).

HBI

Healthy Buildings International Pty Ltd

#### Audits

#### No ER involvement in audit activity including Independent Environmental Audits.

#### **Summary of Environmental Performance**

Concerns have been raised over the last two months after the report of two uncontrolled water discharge incidents (31/5/22 and 13/7/22) to the harbour. The surface water monitoring conducted after the second incident on 13/7/22 was poorly managed, making the assessment of impact to the environment difficult due to a lack of data. The incident remains under investigation and may be subject to scrutiny by the EPA, a further assessment of non-compliance, and the issue of a contractual notice to the Contractor by Sydney Metro

June Quarterly Water Quality monitoring results indicated an exceedance in Cyanide from the WTP discharge. An investigation is in progress to determine the source of the cyanide, and measures implemented to reduce the risk of further cyanide entering the harbour. The quarterly monitoring results have also detected a significant increase in a number of groundwater quality parameters since the last monitoring event, including Polycyclic Aromatic Hydrocarbons (PAH), Calcium, Chloride, Iron, and Total Alkalinity (CaCO<sub>3</sub>). An investigation has not found an explanation for the increase, and improvement to the reporting process have been recommended so trends can be identified as required.

The management of stockpiles and waste classification remains an ongoing issue and will remain a focus with additional hazardous waste identified in excavated soil at the site. The proposed remediation strategy has not yet been communicated to Sydney Metro or the ER.

The demolition of the Hickson Road bridge deck was managed well during the period in terms of noise impacts to surrounding residents (day works only, no complaints) and vibration impacts to the Hickson Road heritage wall, with vibration levels lower than expected. One complaint was received during associated night works involving the removal of steel bridge girders.

#### Looking Forward – Core Focus Areas

- Dewatering of excavations and compliance with the CEMP to reduce the risk of future incidents occurring
- Compliance with water quality parameters in the WDIA during discharge from the WTP
- Management of noise during OOH Work (steel beam removal at night), and noise and vibration impacts during standard construction hours, particularly in relation to demolition of the Hickson Road bridge deck.
- Landowner consent and tree management for planned seawater cooling water installation
- The transfer of water from Line Wide to BESIX Watpac from the surface and Level B6
- The management of works in zones with high-moderate archaeological potential and the reporting of unexpected finds
- The management, storage and disposal of coal tar and asbestos-contaminated spoil
- Completion of the Compliance Tracking Report (CTR) Q1 and Q2 2022.

# 7. Sydenham to Bankstown Sydney Metro Corridor (SMC) and Bankstown Early Works (BEW)

(BEW)			
Project Approval	Contract Package	EPL	Environmental Representative/s
SSI 8256 (S2B)	Southwest Metro Corridor (SMC), Bankstown Early Works (BEW), and Bankstown Station & Additional Corridor (BAC)	#21147	Jo Heltborg
Key Construction an	nd Low Impact Works Activities - During the Period		
Southwest Metro C			
<ul> <li>Wairoa Street I caps complete;</li> <li>Park Street, Car</li> <li>Belmore Triang</li> <li>Loftus Street, B and small sectio</li> <li>Loch Street, Car</li> <li>Punchbowl Hi-r</li> <li>Breust Street, P base of embani</li> <li>Stansfield Aven underway. Prep</li> <li>Bankstown Early W</li> <li>North Terrace O</li> </ul>	Compound: Site offices and amenities, fuel and gas stora	s ongoing. Fi n South Para ioil load-out. Small scop during WE07 allow crane ind DGB com itansfield Av te. Non-dest ge.	nde. . Dewatering tanks (skips) removed. e of underground CSR to complete, 7/WE08 possession). e to lift beam. Tree removal. hplete. re. Stormwater pipe replacement at tructive digging (NDD) for GST posts
<ul> <li>Metro Services Building (MSB): Installation of building façade, internal fit out; services installation.</li> <li>Southern Down Platform: Bus layover handed back. Complete (to be continued under a new contract).</li> <li>Stacey Street Bridge – Countryside, Bankstown: Bolt installation for bridge throw screens ongoing during possessions.</li> <li>Bankstown Station &amp; Additional Corridor (BAC):</li> <li>Low impact investigation works (geotechnical and survey) under Pre-Construction Minor Works Approval (PCMWA).</li> </ul>			
Out of Hours Work:	ctivities Look Ahead		
<ul> <li>Mid-Year Shutd         <ul> <li>SMC so</li> <li>Cumul</li> <li>Enviro</li> </ul> </li> </ul>	own (2-14 July 2022): cope included bridge works, CSR/GST installation etc. ative impacts were discussed during planned mee nmental Representatives (ERs) on 3 <sup>rd</sup> & 24 <sup>th</sup> June. /E07) and WE08 Possessions (13&14 and 20&21 August	-	contractors, Sydney Metro and
<ul> <li>Victoria Road B</li> <li>Hurlstone Park:</li> <li>Campsie: Concrebridge crash be</li> <li>Belmore: Moreclassification ar</li> <li>Lakemba / Wile</li> <li>Punchbowl: GS ongoing.</li> <li>Bankstown: Sta</li> <li>BEW: <ul> <li>Ongoing fit</li> </ul> </li> </ul>	ling for crash beams and retaining walls; works within ridge (on hold pending flood design). Pile caps and installation of throw screens (Church Stre- rete pours for Park Street turnout slabs. CSR completion am works. Swale on hold. eton Street bridge throw screen installation on hold by Park: Alice Street GST installation; new access gate to T installation and drainage work along TEC at Breust St cey Street bridge screens over next possessions. out and completion of MSB facade and surrounds. Sewe	et footbridg n at Lillian Li l (design). I be installed. reet during	e). Culvert works (CCTV) ane and Loch Street. Wairoa Street Belmore triangle: stockpile waste possession. NDD service searching
BAC: o Low impact	t investigation works under PCMWAs.		

#### **ER Inspections**

There were two ER inspections conducted in July 2022 (12<sup>th</sup> & 26<sup>th</sup> July). Actions raised during the inspections were related to the following issues:


- Jerry cans of ULP were stored without secondary containment, and a spill kit was not located within the near vicinity.
   ER actions were addressed during the period.
- Stockpile height at the Belmore Triangle posed an increased risk of dust and or/ sediment runoff offsite. Spoil load-out
  was complete during the period for the stockpile of concern and the action was closed.

#### Photos



Wairoa Street Bridge, Campsie: Jerry cans of ULP were stored without secondary containment. A spill kit was not located within the near vicinity.

Wairoa Street Bridge, Campsie: Accumulated water transported offsite for disposal (high pH).



Wairoa Street Bridge, Campsie: Traffic control was in place to navigate a lane closure on Wairoa Street. Tracking to be monitored ongoing.



Loch Street, Belmore: Full road closure in place on Loch Street Bridge to allow crane to lift beam onto GST alignment under the bridge. A Consistency Assessment was approved for this activity.

HBI Healthy Buildings International Pty Ltd



Breust Place, Punchbowl: During GST post installation an underground stormwater pipe was damaged. Temporary protection measures were established at the time of the incident to reduce the risk of sediment entry into the system.

North Terrace Bankstown: Proposed tree removal locations for BAC.



Stansfield Avenue, Punchbowl: Tree removal and pruning undertaken to facilitate GST and security fencing installation. Two small areas of threatened species *Acacia pubescens* had been identified along the alignment. Barricading and signposting was in place.



BEW MSB Site: Installation of the façade and internal fitout of the MSB continued

Leaders in Environmental Consulting

#### **Endorsed Document/s**

- BAC PCMWA July Shut\_RevD, 1/7/2022
- SMC & BAC CEMP Rev14, 7/7/2022
- SMC & BAC VAMP Rev06, 15/7/2022
- SMC & BAC CSWMP Rev 11, 19/7/2022
- SMC & BAC CNVMP Rev08, 19/7/2022
- SMC & BEW Environmental compliance requirements completion approval Q1 2022, 27/7/2022

#### Non-compliance/ Incidents or Repeat Complaints

Sydney Metro has been providing summaries of complaints to the Department of Planning and Environment (DPE) daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow-up actions often defined in revised reports. Key or repeat items of note are discussed below for SMC, BEW and BAC.

There were no non-compliances reported to the ER during the period.

There were no incidents reported to the ER under Condition A41 of SSI 7400.

There were no Class 3 environmental incidents reported to the ER during the period.

The ER is not aware of any complaints received during July 2022 related to the SMC\_BEW\_BAC works.

#### Audits

No ER involvement in audit activity including Independent Environmental Audits.

#### Summary of Environmental Performance

The avoidance of impact to mapped TECs, and identified threatened species as defined in Revised Environmental Mitigation Measure (REMM) B4 remains an ongoing focus. All TEC and threatened species locations inspected during ER inspections have been appropriately barricaded and sign-posted and workers tool-boxed at pre-start as required.

Erosion and Sediment Control Plans (ESCPs) are consistently reviewed and updated for new work areas and changed activities. The ESCPs demonstrate that Erosion and Sediment (ERSED) issues have been reviewed in detail before applying required controls.

The BAC CEMP has been approved by DPE and the BAC CEMP Sub-plans are with Councils and Heritage NSW (in the case of the CHMP) for consultation. CEMP Sub-plans are due for submission to DPE in August 2022. Low impact works for BAC have commenced, and may continue over possessions up until August, pending assessment and approval. Tree removal may be delayed due to potential non-compliance with approved tree removal numbers identified in the SPIR in station precincts. This matter remains under discussion; a Modification to the planning approval may be required.

Several ancillary facilities are also proposed for use during BAC; the planning approval mechanism for the use of each of these areas is being discussed.

#### Looking Forward – Core Focus Areas

- Management of ERSED controls generally
- Maintenance of tree protection measures, particularly in the vicinity of TECs and threatened species Acacia *pubescens*
- Implementation of the Tree Report during vegetation pruning and removal
- Management of noise during OOH Work including possessions
- Completion of the Q2 2022 Compliance Tracking Report (CTR).

# 8. Marrickville, Canterbury & Lakemba Station Upgrades (MCL)

Project Approval	Contract Package	Environmental Representative/s		
SSI 8256 (S2B)	Marrickville, Canterbury & Lakemba Station Upgrades (MCL) (HSEJV)	Brett McLennan		
Key Construction	Activities During the Period			
-	ssion (2-14 July 2022):			
	OOH) Works, noting external permits were not pr	rovided until the second week		
Marrickville:	oony works, noting external permits were not pr	ovaca anti the second week.		
MSB fit out co	ntinued			
	of the shared user path continued.			
	ng electrical fit out, platform furniture and drainag	10		
	and reticulation services.	5C.		
	instruction continued, excavating and shoring pits	within the CESS commenced		
<ul> <li>Drainage insta</li> </ul>		within the CL33 commenced.		
-	s of shared user path.			
-	s of shared user path.			
Canterbury:	of complex installation and construction of the NAC			
	of service installation and construction of the MSE			
	ation works and furniture installation in the platfo	arm buildings continued.		
	missioning works on platforms			
Concrete pour	s on station.			
akemba:				
	ructural installation, and utilities installation conti			
	ation works, drainage, and platform furniture at the	në platforms.		
-	Activities Look Ahead	•		
	Work WE 7 (13/14 Aug) and WE8 (20/21 Aug) 202			
	of platform / station building fit-out at all stations			
	of MSB construction and/or fit-out at all stations.			
Marrickville				
	<td></td>			
	to Marrickville MSB site.			
	ainment non possession scope.			
<u>Canterbury</u>				
<ul> <li>Canterbury lif</li> </ul>	t installation.			
<ul> <li>MSB concrete</li> </ul>	pours ongoing.			
R Inspections				
There were two EF	R inspections conducted for the period (13 and 27	July). The key issues raised during the inspections		
were:				
All sites				
<ul> <li>Erosion and se</li> </ul>	ediment controls (ESC) required minor updates an	d maintenance.		
Banner mesh	required reattaching to fences and ATF after high	winds.		
Marrickville:				
It was noted t	hat a tipper loaded with soil from the MSB, travel	led with an uncovered load to Charlotte Ave and		
through the "I	No Entry" access. The tipper used back streets to t	travel to the platform to unload. HSEJV were unable to		
provide a TMP for the haulage route and this was raised as NCR-033 against the CTMP.				
	Bunding for groundwater storage drums required maintenance.			
<ul> <li>Weed mainter</li> </ul>				
Canterbury:				
-	hat spoil stockpiling in the MSB required ESC and	the MSB egress points required stabilisation and		
maintenance.				
	hat a parking signpost had been removed pending	g repair.		
	rs required bunding.	J −T −		

 An excavation had collapsed and during stabilisation of the excavation sediment was tracked on Charles Street to Broughton Street. It was noted that a community complaint was received and HSEJV indicated that controls were not in place. Tracking of material was raised as NCR-035.

- It was noted that dump trucks were travelling on Charles Street without loads being covered. The ER reminded HSEJV to cover loads on public streets.
- It was noted that garbage had been thrown into spill kits.
- Management of spoil stockpile at 6 Charles Street was required to prevent spoil entering drainage.


#### Lakemba:

- Plant had been stored outside the approved project boundary (as per the SPIR) and the approved consistency
  assessment for use of the roadway. This damaged the grassed verge and footpath. This was raised as NCR-036
- Stockpiles within the CESS continued to require ESC. This had been raised previously and it was noted that mixing of
  stockpiled material had occurred with no trackability by HSEJV as required in the CEMP. It was noted that the stockpile
  had directly impacted trees within the rail corridor and the root zones of trees outside the corridor. This was raised as
  NCR038.
- A concrete pump for the site was parked within the accessible car spaces. This has been an ongoing issue at this location and was not in compliance with the recent A17 approval for the compound. This was raised as NCR-034.
- It was noted that ESC was not installed within The Boulevarde possession compound.
- Sediment tracking was observed from the Compound to local roads.
- Fuel canisters required appropriate bunding.
- It was noted that egress points still required stabilisation across the Railway Pde Compound, and an unapproved
  egress point was installed with materials placed in the extended compound area without appropriate ESC and
  stabilisation of the area as required under the A17 approval. This was raised as NCR-037.
- Soil had been placed within a mixed waste skip bin and required appropriate removal from site.

Photos



Marrickville MSB – Groundwater drums requiring appropriate bunding.



Marrickville MSB – Construction ongoing



Leaders in Environmental Consulting

Canterbury 6 Charles Street – Maintenance of ESC and stockpile management	Canterbury MSB – rumble grids and egress requiring maintenance
Lakemba – damage to grass verge at Kathleen Street/The Boulevarde	Lakemba- stockpile impacting on trees within the rail corridor.
Attemba – MS egress points required stabilisation	Lakemba extended compound – required ESC and
Endorsed Document/s	stabilisation.
<ul> <li>Canterbury WK02 OOHW</li> <li>SWMP Rev09</li> <li>HMP Rev07</li> <li>VAMP Rev05</li> <li>CEMP Rev08</li> </ul>	
Non-Compliance/ Incidents or Repeat Complaints Sydney Metro has been providing summaries of complaints to	o the Department of Diapping and Environment (DDE) doily
and a summary to the ER. Responses to each complaint have often defined in revised reports. Key or repeat items of note a	been noted in each complaint report, with follow-up actions are discussed below for MCL.
The ER is aware of six new NCRs for the month and 10 compla reported to the ER under condition A36 of SSI 8256.	aints relating to MCL works. There were no incidents for MC
The NCRs are summarised as follows: NCR033 – Uncovered tipper travelling through unapproved h NCR034 – Parking in accessible carpark non-compliant with A NCR035 – Sediment tracking on Charles Street without ESC (C	17 approval (Lakemba).

NCR036 – Plant, equipment and materials stored outside the approved project boundary and without landowner consent (Lakemba).

NCR037 – Use of unapproved access and access stabilisation for Railway Pde compound and extended compound (Lakemba).

NCR038 – Continued lack of stockpile controls and material tracking at Kathleen Street Cess (Lakemba) The complaints are summarised as follows:

- Two noise complaints from Marrickville that were not related to Metro activities.
- Three complaints from Canterbury for noise, noting that alternate accommodation was offered prior to works commencing.
- One noise complaint from Canterbury not related to Metro works.
- Two complaints from Canterbury for property damage and worker behaviour.
- One complaint from Canterbury for sediment tracking (associated with NCR035).
- One compliant from Canterbury for worker parking.

#### Audits

No ER involvement in audit activity including Independent Environmental Audits.

#### ER Closing Comments and Looking Forward – Core Focus Areas

It is noted that a change in project staff has occurred within HSEJV. The ER has held several meetings with HSEJV and Sydney Metro to discuss the ongoing issues and increase in NCRs raised. It is noted that training of staff on the CSSI and the management plans is required. Due to ongoing NCR's and complaints regarding parking and traffic, the ER recommended that an audit of the CTMP be undertaken.

Looking forward:

- Continued implementation checks for CEMP and sub plans, focusing on ESC and parking / traffic impacts
- Compliance Tracking Q1 2022 review and endorsement
- Surveillance during mobilisation and during OOHW
- Independent audit of CTMP.

# 9. Hurlstone Park, Belmore, and Wiley Park Station Upgrades (HBW) and Dulwich Hill Campsie and Punchbowl Station Upgrades (DCP) (Downer)

Project Approval	Contract Dackage	Environmental Representative/s			
Project Approval	Contract Package	Environmental Representative/s			
	Hurlstone Park, Belmore, and Wiley Park Station				
SSI 8256 (S2B)	Upgrades (HBW) (Downer)	Brett McLennan			
	Dulwich Hill Campsie and Punchbowl Station				
Kau Canatanatian A	Upgrades (DCP) (Downer)				
-	ctivities During the Period				
	sion (2-14 July 2022):	had until the cocord week			
	OOH) Works, noting external permits were not provid	ded until the second week.			
Hurlstone Park  Metro Services	Building (MSB) – Trenching works completed, prepa	vision for structural stool installation			
	all structural steel.				
	ng refurbishment works continued, drainage and fur	niture installed			
<ul> <li>GST installation</li> </ul>		Inture instaneu.			
	reconstruction of stairs completed.				
	reconstruction of stans completed.				
Belmore MSB - fit out w	orks continued. GST continued and On-Site Detentio	n (OSD) construction completed			
	ng refurbishment works continued, drainage and fur				
	kiss and ride shelter.	inture instancu.			
Wiley Park					
	nd drainage works continued.				
	ng refurbishment works continued and furniture inst	talled			
<ul> <li>GST installation.</li> </ul>					
	allation of structural steel.				
<ul> <li>Elevator commissioning trials continued.</li> <li>Dulwich Hill:</li> </ul>					
	al steel installation commenced.				
	nstallation, station furniture installed.				
<ul> <li>Station fit out of</li> </ul>					
	IV power completed.				
Campsie:					
	ion of structural steel commenced.				
	allation works continued.				
<ul> <li>Platforms – Station fit out continued.</li> </ul>					
Punchbowl:					
<ul> <li>MSB – Fit out c</li> </ul>	ontinued.				
<ul> <li>Structural steel lift and install at Punchbowl Concourse.</li> </ul>					
<ul> <li>Concourse installation works continued.</li> </ul>					
<ul> <li>Platforms – Sta</li> </ul>	<ul> <li>Platforms – Station fit out continued, drainage and station furniture installed.</li> </ul>				
<ul> <li>Elevator comm</li> </ul>	issioning trials continued.				
<b>Key Construction A</b>	ctivities Look Ahead				
Construction /	fit-out of the MSB's at all stations.				
Construction of the pedestrian bridge, lift shaft, and stairs at Dulwich Hill (pending permits).					
<ul> <li>Commissioning of lift shafts at Hurlstone Park.</li> </ul>					
<ul> <li>GST/CSR routes ongoing.</li> </ul>					
<ul> <li>Landscaping fo</li> </ul>					
<ul> <li>Planning and monitoring the OOHW WE 7 (13/14 Aug) and WE8 (20/21 Aug) 2022</li> </ul>					
ER Inspections					
There was one ER inspections conducted for HBW and DCP on 14 July. The key issues raised during the inspections were:					
<u>All Stations</u>					
<ul> <li>It was noted that banner mesh required reattaching after high winds.</li> </ul>					
Hurlstone Park					

• ER noted stormwater entering the MSB egress could be redirected from the site.

- Noted that ESC was maintained. Asphalt was being delivered, with any excess to assist in stabilising the egress.
   <u>Belmore</u>
- No actions raised.

Wiley Park

 It was noted that a vehicle had parked on wet ground and required grass reinstatement. Minor sediment tracking onto the footpath.

Dulwich Hill

- Vehicle parking and idling were raised with Downer.
- It was noted that tonal movement alarms were used on EWP's
- It was noted that the lift shaft had been graffitied.


Campsie:

It was noted that a section of shade cloth had been graffitied.

Punchbowl:

- It was noted that contractors were parking in the accessible car parks. This was raised as NCR23.
- it was noted that a sub-contractor was using a non-silenced generator to site without noise mitigation. Further inspection of the contractor vehicle indicated that fuel and acids were stored without bunding.

Photos



Punchbowl MSB, concourse and compound.	Hurlstone Park: MSB and platform works		
	<image/>		
Belmore: Plaza and platform works.	Wiley Park, Urunga Pde, MSB and footpath with minor tracking.		
Endorsed Document/s			
<ul> <li>Minor Facility re-endorsement (A19) Campsie</li> </ul>			
<ul> <li>Minor Facility re-endorsement (A19) Belmore</li> </ul>			
Non-compliance/ Incidents or Repeat Complaints			
Sydney Metro has been providing summaries of complaints to the Department of Planning and Environment (DPE) daily and a summary to the ER. Responses to each complaint have been noted in each complaint report, with follow-up actions			
often defined in revised reports. Key or repeat items of no			
reported to the ER under condition A36 of SSI 8256. The NCR is summarised as follows:	ints relating to DCP and HBW works. There were no incidents		
NCR023 – Parking in accessible carparks (Punchbowl) This was initially raised by the ER in May and NCR raised by Downer			
in July after ongoing parking in the accessible car parks.			
The complaints are summarised as follows:			
<ul> <li>Ten complaints raised at Hurlstone Park concerning noise and vibration, scheduled works, consultation, safety, and traffic.</li> </ul>			
<ul> <li>Two complaints from Campsie concerning water outage (not metro related) and idling crane in standard hours.</li> </ul>			
	<ul> <li>Two complaints from Wiley Park regarding traffic and parking, and one general noise and offers for respite.</li> </ul>		
Audits			
Audits No ER involvement in audit activity including Independen			
Audits           No ER involvement in audit activity including Independen           ER Closing Comments and Looking Forward – Core Focus			



- Continued implementation checks for CEMP and sub plans, focusing on ESC and community impacts
- Compliance Tracking Q2 2022 review and endorsement
- OOHWA approvals.
- Independent audit of CTMP.

# 10. Sydney Metro Retained Obligations (SM) /Other

Project App	roval	Contract Package	Environmental Representative/s		
SSI 7400 (C	2S)	Sydney Metro Retained Obligations (SM)	Jo Robertson		
SSI 8256 (S2B)		/Other	JO KODELISOIT		
Key Construe	ction A	ctivities			
SM	The ER is not aware of any CSW related SM construction activities other than as referred to on a package basis above.				
ER Inspection					
SM					
Endorsed Document/s					
SM	Compliance Tracking:				
	CTR-S2B HBW-2021-Q3 and Q4 ER Endorsement Rev B				
	CTR-S2B DCP-2021-Q3 and Q4 ER Endorsement RevB				
	CSW-CTR-LWW-2022-Q1 ER Endorsement RevA Final				
	CTR SSJ Q1 2022				
Non-complia	ance/ Ir	ncidents or Repeat Complaints			
Sydney Metr	ro has k	peen providing summaries of complaints to DPIE d	aily and a summary to the ER. Responses to each		
complaint ha	ave bee	en noted in each complaint report, with follow up	actions often defined in revised reports. Key or		
-		e are discussed below for the respective projects.			
There were r	no non	compliances or incidents raised by the ER against	Sydney Metro for the period.		
Audits					
SM	Sydney Metro is working with the Independent Auditor to deliver the audit program in accordance with the Compliance Tracking and Monitoring Program Report (Rev 2.5). The ER understands that this is still underway.				
Looking Forv	vard –	Core Focus Areas			
SM	• C	ontinued focus on noise impacts by Sydney Metro	and team as the ISD sites approach ground level		
	ir	ncluding review of noise models and potential imp	acts		

#### **11.** Statement of Limitations

Healthy Buildings International (HBI) has prepared this report in accordance with the requirements of Condition A24(I) of the Sydney Metro Conditions of Approval (CSSI 15\_7400) and Condition A26(j) of the Sydney Metro Conditions of Approval (CSSI 17\_8256). The report is for the sole purposes of Department of Planning Industry and Environment (DPIE) and Sydney Metro. It has been prepared based on generally accepted practices and standards at the time it was prepared. No other warranty, expressed or implied, is made as to the professional advice included in this Report. This report did not assess any aspects relating to safety.

Where the Report indicates that information has been provided to HBI by third parties, HBI assumes no liability for any inaccuracies in or omissions to that information.

This Report was prepared based on the conditions encountered and information reviewed for the period of reporting. HBI disclaims responsibility for any changes that may have occurred after this time.

This Report should be read in full. No responsibility is accepted for use of any part of this report in any other context or for any other purpose or by third parties. This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.

Except as required by law, no third party may use or rely on this Report unless otherwise agreed by HBI in writing. Except as specifically stated in this section, HBI does not authorise the use or findings of this Report by any third party

To the extent permitted by law, HBI expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. HBI does not admit that any action, liability or claim may exist or be available to any third party.