

# Spotters on hoses

## The problem

Using hoses to suppress silica dust is not effective. It can expose workers to silica dust and increase the safety risks of working next to heavy plant.

## The solution

Replace 'spotters on hoses' with

- misting systems
- water directly fed to plant and hand-held machinery
- dust extraction fitted to equipment
- extraction ventilation.



Spotters on hoses.



Area misting.



Task misting via a cannon.



Ventilation Dust Extraction Systems placed at the face of the works.



On tool misting.