

A.C.N. 003 270 693

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel : 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

7 April 2022 Ref: 201209-ER\_DPIE-March 2022

Ms Alex McGuirk Compliance Officer– Government Projects Department of Planning Industry and Environment Locked Bag 5022 PARRAMATTA NSW 2124

Dear Alex,

## RE: Sydney Metro - Sydney Metro Western Sydney Airport SSI 10051 – ER Monthly Report for March 2022

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

A.B.N. 39 003 270 693

Condition A32 (k) of the Sydney Metro Western Sydney Airport, SSI 10051 Approval (23 July 2021)

The attached summary details the key activities undertaken by Environmental Representatives for Sydney Metro Western Sydney Airport for the month of March 2022.

Yours sincerely

angues

Rui Henriques Environmental Representative

Cc: Sydney Metro: Hugh Chapman, Jeremy Slattery DPIE: Major Projects Portal

Enclosed: Nil

dney Metro - Western Sydney Airport Ivanced and Enabling Works (AEW) <b>y Construction Activities During the Period</b> Marys Temporary Bus Interchange (TBI): TBI landscaping. Erection of bus shelters, and light and security poles Establishment of a road diversions required for future safe opera Improvements to Lethbridge St and Phillip St intersection to impr construction. Station street closed to through traffic at TBI entry	-
y Construction Activities During the Period Marys Temporary Bus Interchange (TBI): TBI landscaping. Erection of bus shelters, and light and security poles Establishment of a road diversions required for future safe opera Improvements to Lethbridge St and Phillip St intersection to impr construction.	ition of the relocated interchange.
Marys Temporary Bus Interchange (TBI): TBI landscaping. Erection of bus shelters, and light and security poles Establishment of a road diversions required for future safe opera Improvements to Lethbridge St and Phillip St intersection to impr construction.	-
TBI landscaping. Erection of bus shelters, and light and security poles Establishment of a road diversions required for future safe opera Improvements to Lethbridge St and Phillip St intersection to impr construction.	-
Erection of bus shelters, and light and security poles Establishment of a road diversions required for future safe opera Improvements to Lethbridge St and Phillip St intersection to impr construction.	-
Establishment of a road diversions required for future safe operation Improvements to Lethbridge St and Phillip St intersection to impr construction.	-
Improvements to Lethbridge St and Phillip St intersection to impr construction.	-
construction.	
	rove safety of access to TBI and station
Station street closed to through traffic at TBI entry	
	a station boundary
Stormwater installation across Station St. to main trunk line along Utilities cutovers on Station Street.	g station boundary.
Lethbridge and Philip Street roundabout adjustment and pedestr	rian crossing construction
Minor stockpiled spoil load-out in compound.	
TBI open to buses and taxis	
Derwent Street LIW Works	
Geotechnically unsuitable subgrade removed and	
Existing access demolished and new drainage culvert installed	
Driveway alignment formwork completed ready for concrete pour	ır.
rotropolis Services Facility LIW	
Installation of Erosion and Sediment Controls.	
Building structures demolished.	
wer Works	
Establishment of Gipps Street Claremont Meadows Compound co	ompleted
Establishment of Lawson Road Compound ongoing.	Shipleted
Patons Lane works under boring, conduit and cable installation co	ompleted
Kiosk at Claremont Meadows (great western Highway and Gipps	
Greendale Rd Bringelly – conduit proved	
y Construction Activities Look Ahead	
e Construction activities planned for the upcoming period are limite	ed to Advanced Enabling Works (AEW) comprising
Continuation of construction of the Temporary Bus Interchange (	(TBI) at the Station St. Carpark (St Mary's) as
follows:	
<ul> <li>Improvements to Lethbridge St and Phillip St intersection to</li> </ul>	improve safety of access to TBI and station
construction.	
• Stormwater installation across Station St. to main trunk line	•
• Pavement replacement at Station St between Lethbridge and	d the TBI
<ul> <li>Defects rectification works where required</li> </ul>	
Continuation of Power works as follows:	user Dand Dadger in Creati
<ul> <li>Continue establishment of ancillary facilities at 185/195 Law</li> <li>Kiack at Clarement Mandaux (great western Highway and Clarement Mandaux)</li> </ul>	
<ul> <li>Kiosk at Claremont Meadows (great western Highway and Gi</li> <li>String cable along poles on Great Western Highway</li> </ul>	ipps sueet) cable install.
<ul> <li>String cable along poles on Great Western Highway</li> <li>Geotech, services and contamination investigations along Pole</li> </ul>	ower corridor
<ul> <li>Geotech, services and contamination investigations along Po</li> </ul>	
<ul> <li>Commencement of trenching and direction drilling at Wonty</li> </ul>	
<ul> <li>Commencement of trenching and direction drilling at Wenty</li> <li>Commencement of trenching and direction drilling at Cross S</li> </ul>	St – Kemps Creek
• Commencement of trenching and direction drilling at Cross S	
<ul> <li>Commencement of trenching and direction drilling at Cross S</li> <li>Commencement of trenching and direction drilling at Weste</li> </ul>	
<ul> <li>Commencement of trenching and direction drilling at Cross S</li> <li>Commencement of trenching and direction drilling at Weste</li> <li>Completion of 40 Derwent Street LIW Works</li> </ul>	
<ul> <li>Commencement of trenching and direction drilling at Cross S</li> <li>Commencement of trenching and direction drilling at Weste</li> <li>Completion of 40 Derwent Street LIW Works</li> <li>Driveway alignment asphalting.</li> </ul>	
<ul> <li>Commencement of trenching and direction drilling at Cross S</li> <li>Commencement of trenching and direction drilling at Weste</li> <li>Completion of 40 Derwent Street LIW Works</li> </ul>	

## HBI Healthy Buildings International Pty Ltd

## **ER Inspections**

There was one ER Inspection in March 2022 due to weather constraints (ER inspections are on a fortnightly cycle weather permitting):

- 23/03/2022 No key points/ issues raised during this inspection were as follows:
  - Spill kit materials used to clean up a small spill adjacent a light tower at the TBI needed to be removed and an incident report prepared by Ward
  - General litter needed to be removed from the TBI site and adequate rubbish bins provided by Sydney Metro for patrons.
  - o Stockpiles and rubbish needed to be tidied up and where necessary removed from the TBI compound by Ward
  - A small hydraulic spill on Station street needed to be cleaned up and an incident report prepared By Ward
  - Spill booms in the drainage channel at Patons Lane need to be removed and if necessary, disposed of by Power contractor
  - Sediment fence at the Lawson Road Power compound needed to be correctly trenched (dug in)
  - Spill kit signage at the 40 Derwent Road site needed to be placed with all workers informed of where to find spill kit materials in the event of a spill.

Photos





TBI view North along East Lane.



TBI view southeast from East Lane.

TBI view east - works completed.

TBI minor spill cleaned-up near light tower.



Leaders in Environmental Consulting

## HBI Healthy Buildings International Pty Ltd



St Marys Lift relocation site hoarding tree removal and stormwater encasement Low Impact Works application

### HBI Healthy Buildings International Pty Ltd

 Elizabeth Drive and Badgerys Creek Road roundabout forth leg to SM (SCAW) works corridor Low Impact Works Application

The following documents were provided for information or reviewed with comments provided to Sydney Metro.

- TBI DNVIS addendum for Philip and Lethbridge intersection improvement works
- TBI OOHW 01 April 2022 submission
- Roads CEMP for Elizabeth Drive and Badgerys Creek Road roundabout forth leg to SM (SCAW) works corridor.
- LIW 40 Derwent Road Access Upgrade nightworks
- Power DNVIS
- Power CEMP proposed updates
- Power OOHW 001 Greater Western Highways and Gipps overhead cable works
- SM approved Integrated Project Office Geotechnical Investigations Low Impact Works application
- SM approved GHD Bringelly RAAF DSI- Bringelly Low Impact Works application
- SM approved GHD Geotech Investigations Geotech investigation- St Marys Low Impact Works application
- SM approved Cardno Non- invasive Survey works- St Marys Low Impact Works application
- SM approved Cardno Non- invasive Survey works- Werrington Low Impact Works application
- SM approved Cardno Non- invasive Survey works- Werrington Schools Low Impact Works application
- SM approved Cardno Survey works- Bringelly Low Impact Works application
- SM approved Cardno Survey works- Claremont Meadows Low Impact Works application
- SM approved Cardno Survey works- Bringelly Low Impact Works application
- SM approved RPS Non-invasive survey works- St Marys Low Impact Works application
- SM approved St Marys Station Lift relocation geotechnical investigations Low Impact Works application
- SM approved Utilities investigation- St Marys Harris Street Forrester Rd & Queen St Low Impact Works application
- SM approved RPS Utilities investigation-Aerotropolis station Low Impact Works application
- SM approved M2A Biodiversity surveys- Orchard Hills Low Impact Works application
- SM approved M2A Biodiversity surveys- Orchard Hills Low Impact Works application

#### Complaints / Incidents / Non-compliance

Six (6) complaints were received with four (4) relating to the CSSI:

- 21/03/2022 Complaint about the Contractor using her driveway, the restoration of her nature strip and poor worker behaviour near her property.
- 21/03/2022 Complaint about complained about interrupted water supply between 18-20 March and contacted Sydney Water.
- 23/03/2022 Complaint about a traffic controller's behaviour on site when the stakeholder was accessing her property
- 24/03/2022 Complaint about the Contractor on nature strip causing damage.

All complaints were closed out with the stakeholders appropriately and measures were taken to prevent recurrence

One (1) non-compliances were reported for the Period:

• A non- compliance against Conditions of Approval and E41 was reported to the ER relating to works conducted outside Standard Construction Hours without adequate approvals in place.

Three (3) incidents were reported for the period:

- TBI Station St Stormwater relocation works Minor hydraulic spill
- TBI temporary diesel powered lighting tower Minor diesel spill
- Power minor diesel spill on Patons Lane due to a fuel system leak from a water cart

#### Audits (specific to packages reported in this report)

Nil this period

## Looking Forward – Core Focus Areas

- Monitor commencement of AEW Power Out of hours Works
- Review AEW St Marys Station Lift Relocation

Contract Package	Environmental Representative/s
Sydney Metro - Western Sydney Airport	Rui Henrigues/ Jo Robertson/Alex Gale
Station Boxes and Tunnelling (SBT)	Rui Henriques/ Jo Robertson/Alex Gale
Key Construction Activities During the Period	
<ul> <li>Nil Construction Activities</li> </ul>	
Key Construction Activities Look Ahead	
<ul> <li>St Marys construction site establishment preparation works</li> </ul>	
<ul> <li>Establish ERSED Controls excluding sediment basins</li> </ul>	
<ul> <li>Hoardings fences and barricading</li> </ul>	
<ul> <li>Station Plaza demolition</li> </ul>	
ER Inspections	
There were no site Inspections conducted by the ER in February	2022.
Photos	
NA	
Endorsed Document/s	
The following documents were endorsed by the ER:	
<ul> <li>Low Impact Works - St Marys Construction Site geotechnical</li> </ul>	investigations and utility investigations
The following documents were provided for information or revie	wed:
<ul> <li>Preparatory Construction Environmental Management Plan</li> </ul>	
<ul> <li>SM approved Claremont Meadows Facility geotechnical investigation</li> </ul>	stigations and surveying Low Impact Works application
<ul> <li>SM approved Orchard Hills Facility geotechnical investigation</li> </ul>	ns and surveying Low Impact Works application

SM approved Orchard Hills Facility geotechnical investigations and surveying Low Impact Works application

Complaints / Incidents / Non-compliance

Not relevant to this period

## Audits (specific to packages reported in this report)

No audits were conducted during the reporting period.

# Looking Forward – Core Focus Areas

SBT Preliminary CEMP Monitor Station Plaza demolition works

#### **Statement of Limitations**

Healthy Buildings International (HBI) has prepared this report in accordance with the requirements of Condition A32 (k) of the Sydney Metro Western Sydney Airport, Concept and Stage 1 SSI 10051 Approval (23 July 2021). The report is for the sole purposes of Department of Planning Industry and Environment (DPIE) and Sydney Metro. It has been prepared based on generally accepted practices and standards at the time it was prepared. No other warranty, expressed or implied, is made as to the professional advice included in this Report. This report did not assess any aspects relating to safety.

Where the Report indicates that information has been provided to HBI by third parties, HBI assumes no liability for any inaccuracies in or omissions to that information.

This Report was prepared based on the conditions encountered and information reviewed at this time. HBI disclaims responsibility for any changes that may have occurred after this time.

This Report should be read in full. No responsibility is accepted for use of any part of this report in any other context or for any other purpose or by third parties. This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.

Except as required by law, no third party may use or rely on this Report unless otherwise agreed by HBI in writing. Except as specifically stated in this section, HBI does not authorise the use or findings of this Report by any third party

To the extent permitted by law, HBI expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. HBI does not admit that any action, liability or claim may exist or be available to any third party.