Suite 2.06, Level 2 29-31 Solent Circuit Baulkham Hills NSW, 2153 Australia

Tel: 61 (02) 9659-5433 E-mail: <u>hbi@hbi.com.au</u> Web: <u>www.hbi.com.au</u>

Stacy Warren
Director Infrastructure
Department of Planning and Environment
GPO Box 39
SYDNEY NSW 2001

7 September 2018

Ref: 170108-ER-DPE-Aug 18-SYAB CS NCW IW

Dear Stacy

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 – ER Monthly Report for August 2018 – SYAB, CS, NCW, SSJ, and Investigation works

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications (MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), and MOD 3_Martin Place Metro Station (22 March 2018); and
- As required by the subsequent appointment as the approved Environmental Representative (17 February 2017);

The attached summary details the following key activities undertaken by ERs for Sydney Metro – City and South West Chatswood to Sydenham during the month of **August 2018** for Sydney Yard Access Bridge, Sydenham Station Junction, Central Station Works, Northern Corridor Works and Investigation Works.

Yours sincerely

Jo Robertson

Environmental Representative

Cc: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam Koutsamanis, Margarita Ognjanovic, Andrew Hendy, Simon Fisher,

Cc: Swati Sharma, Rob Sherry, Kate Moore, Larry Weiss, Julie Dickson

Summary of Contract Pac	cages	Environmental Representative/s	
Sydney Yard Access Bridge (SYAB) (Early Works package)		age)	
Sydenham Station Junction (SSJ) (Early works and Main works)		ain works) Annabelle Reyes	
Central Station (Early Works and Main Works)			
Investigation Works			
Northern Corridor (NCW) (Early Works package)		Annabelle Reyes / Erran Woodward	
Alternate for all packages		Jo Robertson	
Key Construction Activitie	s		
Sydney Yard Access Bridge (SYAB)	SYAB Defect wo	rks	
Sydenham Station	The following minor works were undertaken:		
Junction (SSJ)	> Installation of safe work zones along Burrows Avenue and Bolton Street to		
	prepare for the new station plaza		
	Installation of e	lectrical and water services on the rail bridge structure above	
	the entry road	o Fraser Park	
	Location, inspe	ction and installation of new services routes	
	Clearing of veg	etation inside the rail corridor	
	Out of Hours W	orks	
	 Plant and equipment will be delivered up until midnight 		
	o Geote	chnical investigations	
	 Installation of new signals, and over-head wiring, footings and 		
	structures		
	 Installation of new services under the railway line 		
	 Installation of signal infrastructure 		
	 Vegetation clearing inside the rail corridor 		
Northern Corridor Works	The following works wer	e conducted:	
(NCW)	Installation of security fencing		
	 Each weekend in August 2018 the following works were conducted: 		
Installation between Brand Street and Mowbray Road on the		ation between Brand Street and Mowbray Road on the	
	weste	n side is planned, between 7am-5pm each day.	
	Drainage improvements between Brand and Drake streets:		
	 Delivery of oversized equipment (between 10am-2pm) to the Drake Street site. 		
	 Parking restrictions were in place Drake Street for safe 		
	manoeuvring.		
	 13 August-7 September - Piling to prepare for excavation during 		
	standard work hours.		
	o 25-27	August - Piling to prepare for excavation 24-hours a day	
		the Sydney Trains rail maintenance weekend, when trains	
		ot running.	
		or work between Waitara and Waverton stations:	
	Signall	ing and electrical upgrades including cable pulling and the	
	_	ition of new overhead wiring, footings, steel structures	
), and connecting booms on masts.	
	· ·	tion trimming or removal	
	Out of hours we		
		ugust – Drainage improvements and vegetation removal.	
Central Station		nd subplans by DPE was granted on 3 August 2018.	
	Major construction commenced in early August 2018 with the closure of Platforms		
	13-14 and 15 to make way for construction of the new underground Sydney Metro		
	platforms. Construction of the new stairs on Platforms 20-21 and Platforms 22-23		
	-	ith completion expected late December 2018.	

ᆫ	ı	ŀ	₹	ı

The fell	lowing construction works have commenced:
	Central Station Precinct
	Visual inspections within Central Station and on adjoining streets
	o Identification of utilities using cameras, hand tools and survey
	equipment within Central Station and on adjoining streets.
>	Platforms 10-11 & 12
	 Installation of footings along Platform 11
	 Saw cutting sections of Platform 12 in preparation for installing
	canopy hoarding
	 Saw cutting and installation of new overhead wiring structures on
	Platform 11
>	Platforms 13, 14 & 15
	 Erection of temporary fencing and closed access to Platforms 13-14
	and 15
	 Stripping of Platforms 14-15
	 Removal of railway tracks and overheads on Platform 15
	 Relocation of furniture on closed platforms
>	Platforms 20-21 and 22-23
	 Drilling within the hoarded areas to prepare for the new stairs to be
	installed (customer access maintained)
>	Sydney Yard
ĺ	Removal of vegetation
	 Installation of temporary site office, services, overhead wiring
	structures and new fencing
Investigation Works Nil	on actual to and new remains
IIIVCSCIBACION WOLKS IVII	

ER Inspections		
SYAB	No more inspection. SYAB construction is completed.	
SSJ	Nil	
NCW	Nil	
Central Station	There were two ER inspection conducted in August 2018. The DPE Compliance Officer attended the inspection on 08/08/2018.	
	 ER Inspection reports have been prepared and issued to Sydney Metro and the CSMW Contractor. Actions identified during the inspections comprised: CSMW ER Inspection 03 – 08/08/2018 – erosion and sedimentation controls, and reduction of speed (from 20 kph to 10 kph) at SYAB to reduce noise. CSMW ER Inspection 04 -22/08/2018 – no issues observed during this inspection. Various notes were made in the reports reflecting commitments made by the Laing 	
	O'Rourke.	
Investigation Works	Nil	

Endorsed Document/s		
SYAB	Nil	
SSJ	The following documents were reviewed and endorsed by the ER: Consistency Assessment Sydney Water Laydown Area (Carrington Road) Rev 1 Draft Pre-construction Compliance Report (Rev 3) Tree Impact Assessment Report - Rail Corridor - Rev 3 SSJ Revised Tree Assessment Report for the rail corridor Rev 3 CNVIS Rev C SMCSW1SSJ - CTMP Rev 3 ER Endorsement SSJ Minor Works WE10 Updated HIP, including treatment of conditional ER endorsement of the 2017 HIP. Pre-Construction Compliance Report - Appendix A - SSJ The following documents were reviewed only: Interchange Access Plan for SSJ	
NCW	The following documents were reviewed and endorsed by the ER: Tree Report Revision 000 - NCW works Tree Impact Assessment Report Revision 01- NCW Portion NCW Portion 7 ECM Laydown Areas NCW OOHW 016- NCW Fencing Works The following documents were reviewed only: OOHWA 017 - MW12 (Rev 01)	
Central Station	The following documents were reviewed and endorsed by the ER: Hi-Rail Access George Street, The Rocks - Addendum to CSMW 06 Consistency Assessment Access Points and Laydown Area OOHW 007 WE09-WE11 OOHW 008 WE11 to WE24 OOHW WK06-WK08 OOHW Application 006_100818 Pre-Construction Compliance Report - Appendix A - CSMW CSMW Business Management Plan Rev 2 and Rev 3 CSMW CTMP Rev 4 Endorsed with condition The following documents were reviewed only: Sustainability Management Plan Pollution Incident Response Management Plan CTMP Rev 4 - confirmation of endorsement conditions	
Investigation Works	Nil	

Non-compliance/ Incidents or Repeat Complaints	
SYAB	Nil
SSJ	Nil
NCW	Nil
Central Station	There were two minor oil spill incidents occurred on the following dates: 26 August 2018 at South of Platform 16 on Track 16. During backfilling of an excavation, a hose of a whacker packer broke causing a minor oil spill on the ballast. The machine was immediately shut down and decommissioned. Biodynamic absorbent material from the on-site spill kit was utilised to soak up the spill. 90 August 2018 at Sydney Yard adjacent to the rolling stock building. During footing excavation for new overhead wiring structures, a hydraulic hose of a 6t excavator broke, causing hydraulic oil to spill onto the hardstand area. The machine was immediately shut down. The leak was contained within the footprint of the excavator tracks. Biodynamic absorbent material from the on-site spill kit was utilised to soak up the spill. Additional spill mats were placed on top of the absorbent material to ensure any drips from the excavator undercarriage were collected.
Investigation Works	Nil

Audits	
SYAB	Nil
SSJ	Nil
NCW	Nil
Central Station	Nil
Investigation Works	Nil
Looking Forward	
SYAB	Core Focus Areas for the coming month are:
	 Compliance Tracking Review (Q2 2018) evidence close out of conditions relevant to SYAB (as per the staging report)
SSJ	 Core Focus Areas for the coming month are: Demolition of the heritage building on Platform 6, implementation of heritage mitigation measures. Site establishment and setting up of site compound at Fraser, implementation of the ancillary facility management plan. Clearing of vegetation inside the rail corridor, implementation of the tree impact assessment report.
NCW	Core Focus Areas for the coming month are: Out of hours works – cumulative noise Clearing of vegetation inside the rail corridor, implementation of the tree impact assessment report.
Central Station	Core Focus Areas for the coming month are: Implementation of heritage management plan in particular for the demolishing of Platforms 14-15. Implementation of archaeological method statements and noise and vibration monitoring, as well as implementation of mitigation measures having regard to the excavation and drilling of the Metro Station box and Olympic stairs work.
Sydney Metro	Sydney Metro Compliance tracking review on retained obligations.
Other	
Nil	