Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Erica van den Honert Director Infrastructure Management Department of Planning and Environment GPO Box 39 SYDNEY NSW 2001 27 May 2019

Ref: 170108-ER-DPE-Apr 19-SSJ CS NCW IW R1

Dear Erica

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15\_7400 – ER Monthly Report for April 2019 – SYAB, CS, NCW, SSJ, Investigation works, and S2B

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15\_7400 Approval (9 January 2017) and associated modifications (MOD1\_Victoria Cross and Artarmon (18 October 2017), MOD2\_Central Walk (21 December 2017), MOD4\_Sydenham Station and Metro Facility South (13 December 2017), MOD 3\_ Martin Place Metro Station (22 March 2018), MOD 5\_Blues Point Acoustic Shed (2 November 2018) and MOD 6 Administrative Changes (21 February 2019);
- Condition A26(j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI\_8256 Approval (12 December 2018); and

The attached summary details the following key activities undertaken by ERs for Sydney Metro – City and South West Chatswood to Sydenham (C2S) during the month of **April 2019** for Sydney Yard Access Bridge, Sydenham Station Junction, Central Station Works, Northern Corridor Works, and Investigation Works.

It also provides a summary in relation to the Sydney Metro - Sydenham to Bankstown (S2B) for the same period.

Yours sincerely

Jo Robertson

**Environmental Representative** 

Sydney Metro Cc: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam

Koutsamanis, Margarita Ognjanovic, Andrew Hendy, Simon Fisher,

DPE Cc: Elizabeth Williamson, Kate Moore, Alice Pryke

IEP Cc: Larry Weiss, Julie Dickson

Summary of Contract Packages		Environmental Representative/s		
Sydney Yard Access Bridge (SYAB)		Jo Robertson		
Sydenham Station Junction (SSJ)		Alberto Paludetto		
Central Station		Alberto Paludetto		
Investigation Works		Jo Robertson		
Northern Corridor (NCW)		Peter Hatton		
Sydenham to Bank (SMEW was S2B)	stown Sydney Metro Early Works	Jo Robertson		
Line Wide (Tallawo	ng to Bankstown)	Peter Hatton		
Key Construction A	Activities			
Sydney Yard Access Bridge (SYAB) Sydenham Station	<ul> <li>Construction works completed in May 20</li> <li>Final Compliance Report underway.</li> <li>Combined Service Route construction</li> </ul>			
Junction (SSJ)	support construction activities and mater Strip out of 11 Sydenham Road Marrickvi lead paint removal continuing.	int. Contraflow traffic management in operation, to rials delivery lle buildings ongoing; additional asbestos removal, aqueduct at the Sydenham Pumping station has		
Northern Corridor	■ 11/33 power cutover;			
Works (NCW)	<ul> <li>Overhead wiring overlap works;</li> </ul>			
	<ul><li>Cess drainage;</li></ul>	=		
	Signal construction;			
	<ul> <li>Dry track build (ballast, rail and sleepers);</li> </ul>			
	<ul> <li>Nelson Street pier demolition;</li> </ul>			
	<ul> <li>Combined service routes and Signal base construction; and</li> </ul>			
	<ul> <li>Brand Street crossing investigation works.</li> </ul>			
Central Station	The SYAB Bridge is in operation for use by			
	<ul> <li>Piling with continuous flight auger drilling rigs, and pile cropping is ongoing</li> </ul>			
	<ul> <li>Excavation at the northern end of the Metro Box is ongoing, with a blinding layer construction completed.</li> </ul>			
	All chacological excavations.			
	<ul> <li>Site and soil classifications ongoing.</li> </ul>			
	Ring beam installation.			
	<ul> <li>Northern Concourse works including, decommissioning of stairs, provision of alternate access to lower levels.</li> </ul>			
		st Platforms hazardous materials removal .		
	<ul> <li>Plunge columns in southern area of Metr</li> </ul>			
Investigation Works	Nil	0.000		
SMEW	<ul> <li>Early investigation works (low impact wo investigations.</li> </ul>	rk) including survey, bridge inspections and site		
Line Wide	■ Nil			

ER Inspections		
SYAB	No more inspections required. SYAB is now in operation.	
SSJ	There were two inspections conducted by the ER in April 2019. Issues identified during inspections included erosion and sedimentation controls, compliance to water quality discharge process. Managing water inflow to Bolton St laydown from outside the project, contaminated building debris stabilisation. The ER Inspection reports were prepared and issued to Sydney Metro and the SSJ Contractor, the John Holland Laing O'Rourke Joint Venture (JHLORJV).	
NCW	There were no ER inspections required in April 2019.	
Central Station	There were two ER inspections conducted in April 2019. Issues identified during the inspections included improvements in temporary site water management processes prior to the installation of a dedicated water treatment plant. ER inspection reports have been prepared and issued to Sydney Metro and the CSMW Contractor Laing O'Rourke (LOR). Various notes were recorded in the reports reflecting commitments made by LOR.	
Investigation Works	No inspections were required in April 2019.	
SMEW	No inspections were required in April 2019.	
Line Wide	No inspections were required in April 2019.	
Endorsed Docume		
SYAB	■ Nil	
SSJ	■ Nil	
NCW	Construction Ancillary Facilities Management Plan (Rev 08)	
Central Station	■ Nil	
Investigation	■ Nil	
Works		
SMEW	<ul> <li>General Site Wide Minor Works Approval</li> <li>OOHW Application for Survey Work 15-19th April</li> </ul>	
Line Wide	Nil	
	Incidents or Repeat Complaints	
Sydney Metro has complaint have be repeat items of no	been providing summaries of complaints to DPE daily and a summary to the ER. Responses to each een noted in each complaint report, with follow up actions often defined in revised reports. Key or one are discussed below for the repective projects.	
SYAB	Nil	
SSJ	Incidents and complaints for this site during the period included a minor hydraulic oil spill on site; and potential vibration impacts on commercial premises during demolition at 11 Sydenham Road Marrickville. Vibration monitoring has been undertaken demonstrating compliance well levels well below the 7.5mm/s threshold.	
NCW	A number of complaints were made in association with the NCW Portion 7A works regarding noise and vibration, and traffic management.	
Central Station	<ul> <li>Of note:         <ul> <li>A business adjacent to the Bounce Hotel expressed concerns about business viability and subsequent loss of customers with the Hotel closing. Small business support discussions with this business are ongoing.</li> <li>A different business owner was unhappy with initial traffic controller diverting pedestrian traffic towards business location. The pedestrian traffic flow was altered.</li> <li>Sydney Trains noted the location of an elevated working platform was interfering with commuter flows. The EWP was relocated.</li> </ul> </li> </ul>	
Investigation Works	Nil	
SMEW	There was a noise complaint from low impact geotechnical work at Campsie Station during standard construction hours. Work ceased before noise monitoring could be undertaken. Noise monitoring was undertaken subsequently when work resumed demonstrating compliance.	
Line Wide	Nil	

Audits		
SYAB	Nil	
SSJ	Nil. Note that the SSJ JV is currently preparing an updated internal audit program (separate to the Independent Environmental Audit program required by Planning Approval Condition A37).	
NCW	Nil	
Central Station	Nil	
Investigation	Nil	
Works		
SMEW	Nil	
Line Wide	Nil	
Looking Forward	- Core Focus Areas	
Sydney Metro	<ul> <li>Staging report for the SMEW (as the first stage in S2B), and also Line Wide.</li> </ul>	
SYAB	<ul> <li>Completion of compliance reporting.</li> </ul>	
SSJ	<ul> <li>Continuing scaffold construction for aqueduct with Sydenham Drainage Pit.</li> </ul>	
	<ul> <li>Investigation beneath slab at 11 Sydenham Rd Marrickville</li> </ul>	
	<ul> <li>New EPL to be issued for SSJ, post demolition at 11 Sydenham Rd Marrickville</li> </ul>	
	<ul> <li>Flood management and the flood report compliance.</li> </ul>	
	<ul> <li>Station Design and Precinct Plan development and submission.</li> </ul>	
	<ul> <li>HV works within project and from Gleeson Ave to the Project, taking place through OOHW</li> </ul>	
	protocol.	
	Drainage works at Sydenham station.	
NCW	<ul> <li>Management of noise and vibration during possession works.</li> </ul>	
Central Station	Noise and vibration monitoring.	
	<ul> <li>Dust management.</li> </ul>	
	<ul> <li>Update of archaeological method statement (AMS), and implementation of archaeological</li> </ul>	
	method statements and exhumation management plan.	
	<ul> <li>Road use changes and closures at Randle Street and nearby streets east of Central Station.</li> <li>Stockpile management.</li> </ul>	
	Bounce Hotel strip out and demolition.	
	Station Design and Precinct Plan development and submission.	
	<ul> <li>Development of the Heritage Interpretation Plan.</li> </ul>	
	<ul> <li>Update to Heritage Register for Northern Concourse deconstruction and heritage asset</li> </ul>	
	recovery.	
	<ul> <li>Hazardous materials removal to the Eastern Suburbs Rail Concourse and within ghost</li> </ul>	
	platforms.	
SMEW	Early investigations.	
	Pre commencement approval documentation reviews.	
	<ul> <li>Approval of low impact OOHW under the OOHW Protocol.</li> </ul>	
	<ul> <li>Updates to the Construction Traffic Management Framework.</li> </ul>	
Line Wide	Planning for early investigations.	
	Strategy for delivery of multiple approvals.	
	<ul> <li>Input to pre commencement approval documentation.</li> </ul>	