Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Erica van den Honert Director Infrastructure Management Department of Planning and Environment GPO Box 39 SYDNEY NSW 2001 04 June 2019
Ref: 170108-ER-DPE-May 19-SSJ CS NCW IW LW S2B

Dear Erica

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15\_7400 – ER Monthly Report for May 2019 – SYAB, CS, NCW, SSJ, Investigation works, and S2B

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15\_7400 Approval (9 January 2017) and associated modifications (MOD1\_Victoria Cross and Artarmon (18 October 2017), MOD2\_Central Walk (21 December 2017), MOD4\_Sydenham Station and Metro Facility South (13 December 2017), MOD 3\_ Martin Place Metro Station (22 March 2018), MOD 5\_Blues Point Acoustic Shed (2 November 2018) and MOD 6\_ Administrative Changes (21 February 2019);
- Condition A26(j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI\_8256 Approval (12 December 2018); and

The attached summary details the following key activities undertaken by ERs for Sydney Metro – City and South West Chatswood to Sydenham (C2S) during the month of **May 2019** for Sydney Yard Access Bridge, Sydenham Station Junction, Central Station Works, Northern Corridor Works, and Investigation Works.

It also provides a summary in relation to the Sydney Metro - Sydenham to Bankstown (S2B) for the same period.

Yours sincerely

Jo Robertson

**Environmental Representative** 

Sydney Metro Cc: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam

Koutsamanis, Margarita Ognjanovic, Andrew Hendy, Simon Fisher,

DPE Cc: Elizabeth Williamson, Kate Moore, Alice Pryke

IEP Cc: Larry Weiss, Julie Dickson

| Summary of Contract Packages                                  |   | Environmental Representative/s   |
|---|---|--|
| Sydney Yard Access Bridge (SYAB)                              |   | Jo Robertson   |
| Sydenham Station Junction (SSJ)                               |   | Alberto Paludetto  |
| Central Station   |   | Alberto Paludetto  |
| Investigation Works   |   | Jo Robertson   |
| Northern Corridor (NCW)                                       |   | Peter Hatton   |
| Sydenham to Bankstown Sydney Metro Early Works (SMEW was S2B) |   | Jo Robertson   |
| Line Wide (Tallawor   | ng to Bankstown)  | Peter Hatton   |
| <b>Key Construction A</b>                                     | ctivities   |  |
| Sydney Yard<br>Access Bridge<br>(SYAB)                        | <ul> <li>Construction works completed in May 20</li> <li>Final Compliance Report completed May</li> </ul>   | 2019.  |
| Sydenham Station<br>Junction (SSJ)                            | <ul> <li>11 Sydenham Road - Slab removal and as</li> </ul>  | cent Fraser Park compound. cavation works ongoing. ion. nam Station footprint. urse entry and Station platform reinstatement. sbestos and lead management. aqueduct at the Sydenham Pumping station. |
| Northern Corridor   | Overhead wiring overlap works.  |  |
| Works (NCW)   | <ul> <li>Cess drainage.</li> <li>Signal construction.</li> <li>Dry track build (ballast, rail and sleepers).</li> <li>Nelson Street pier demolition.</li> <li>Combined service routes and Signal base</li> <li>Brand Street crossing investigation works</li> </ul>   | construction.  |
| Central Station   | reinforcing and concrete pouring works.  Archaeological testing and clearance is or Piling with continuous flight auger drilling Contamination investigations are ongoing Excavation ,segregation,stockpiling and to Concrete recycling with steel and masonr Demolition of stairs from the upper Nortl Hoarding facing Chalmers St was establis Bounce Hotel soft strip has commenced. | ngoing with the relevant permits in place. grigs was ongoing but is now complete. gesting of of materials is ongoing. y recovery continues. hern Concourse area to the lower Concourse.              |
| Investigation   | ■ Nil   |  |
| Works   |   |  |
| SMEW  | <ul> <li>Early investigation works (low impact wo investigations.</li> </ul>  | rk) including survey, bridge inspections and site  |
| Line Wide   | ■ Nil   |  |

|  | No more inspections required. SYAB is now in operation.  |  |
|--|--|--|
|  |  |  |
| .  | There were three inspections conducted by the ER in May 2019. Issues identified during   |  |
| l i  | inspections included mud tracking from works areas onto public roads, concrete washout   |  |
|  | management and dust suppression. The ER Inspection reports were prepared and issued to   |  |
|  | Sydney Metro and the SSJ Contractor, the John Holland Laing O'Rourke Joint Venture (JHLORJV).  |  |
|  | There were no ER inspections required in May 2019. Next inspection scheduled for 22 June   |  |
| Central Station There were three ER inspections conducted in May 2019 Significant archaeological investigations. |  |  |
|  | works are ongoing under permit on a portion of the site. Contamination site investigations and   |  |
|  | materials classification were ongoing through the period.  |  |
| E  | ER inspection reports have been prepared and issued to Sydney Metro and the CSMW Contractor  |  |
| l  | Laing O'Rourke (LOR). Various notes were recorded in the reports reflecting commitments made   |  |
| k  | by LOR.  |  |
| Investigation N  | No inspections were required in May 2019.  |  |
| Works  |  |  |
| SMEW N   | No inspections were required in May 2019.  |  |
| Line Wide  | No inspections were required in May 2019.  |  |
| Endorsed Document/   |  |  |
| 31718  | ■ Nil  |  |
| SSJ •  | ■ Nil  |  |
| NCW •  | ■ Nil  |  |
| Central Station  | ■ Nil  |  |
| mvestigation   | ■ Nil  |  |
| Works  |  |  |
| SMEW •   | Conv. 665 Survey Works and Site inspection   |  |
| •  | SSJ1A1B-PCMW-014 T1C Belmore and Lakemba Rev 1   |  |
| •  | 55311A1B-0011W-007 Translated Survey   |  |
| •  | <ul> <li>Community Communications Strategy - SSJ and SMEW</li> </ul>   |  |
| •  | <ul> <li>Business Management Plan - SSJ and SMEW</li> </ul>  |  |
| •  | Construction Son and Water Management Flan Nev 1   |  |
| •  | othices wandement strategy han her s   |  |
|  | 33371B COTTVITAPOGG Survey Work Syderman to Campsic  |  |
| Line Wide  | - 1411   |  |
|  | idents or Repeat Complaints  |  |
|  | en providing summaries of complaints to DPE daily and a summary to the ER. Responses to each   |  |
| •  | noted in each complaint report, with follow up actions often defined in revised reports. Key or  |  |
| •  | are discussed below for the repective projects.  |  |
|  | Nil  |  |
| SSJ I  | Incidents and complaints for this site during the period included:   |  |
|  | A million concrete waste spin melacite on site.  |  |
|  | <ul><li>External vehicle access issue due to trucks blocking adjacent access points.</li><li>Noisy night works, and a resident's site security gate being left open.</li></ul> |  |
| NCW A  | A number of complaints were made in association with the NCW Portion 7A works regarding noise  |  |
|  |  |  |
|  | and vibration, and traffic management.  No incident reports were issued in reporting period. A number of complaints were received  |  |
|  | including the following:   |  |
| '.   | <ul> <li>Complaints about dust and noise emisions from platform works. Additional controls reported</li> </ul>   |  |
|  | by the Contractor included the use of noise blankets and dust suppression measures.  |  |
|  |  |  |
|  | rather cumulative impacts from nearby works.   |  |
|  |  |  |
|  | confirmed that hazardous materials and soil removal are undertaken by licensed contractors.  |  |
|  | Air monitoring is in place during removal. Results to date are below any detectable limits.  |  |
|  |  |  |

|                   | station staff to manage any materials movements through the station.   |  |
|-------------------|--|--|
| Investigation     | Nil  |  |
| Works             |  |  |
| SMEW              | No incident reports were issued in reporting period. A repeat complaint in relation to service                 |  |
|                   | location works (potholing) was received. The project confirmed that notification had occurred and              |  |
|                   | also undertook noise monitoring that demonstrated compliance.  |  |
| Line Wide         | Nil  |  |
| Audits            |  |  |
| SYAB              | Nil  |  |
| SSJ               | Nil.   |  |
| NCW               | Nil  |  |
| Central Station   | Nil  |  |
| Investigation     | Nil  |  |
| Works             |  |  |
| SMEW              | Nil  |  |
| Line Wide         | Nil  |  |
| Looking Forward – | Core Focus Areas   |  |
| Sydney Metro      | <ul> <li>Staging report for the SMEW (as the first stage in S2B), and also Line Wide.</li> </ul>               |  |
| SYAB              | <ul> <li>Nil- package complete – this will be removed from the next DPE report.</li> </ul>                     |  |
| SSJ               | <ul> <li>Continuing scaffold construction for aqueduct with Sydenham Drainage Pit.</li> </ul>                  |  |
|                   | <ul> <li>Investigation beneath slab at 11 Sydenham Rd Marrickville</li> </ul>                                  |  |
|                   | <ul> <li>New EPL to be issued for SSJ, post demolition at 11 Sydenham Rd Marrickville</li> </ul>               |  |
|                   | Flood management and the flood report compliance.  |  |
|                   | Station Design and Precinct Plan development and submission.   |  |
|                   | <ul> <li>HV works within project and from Gleeson Ave to the Project, taking place through OOHW</li> </ul>     |  |
|                   | protocol.  |  |
|                   | <ul> <li>Drainage works at Sydenham station.</li> </ul>  |  |
| NCW               | <ul> <li>Management of noise and vibration during possession works.</li> </ul>                                 |  |
| Central Station   | Noise and vibration monitoring.  |  |
|                   | <ul> <li>Dust management.</li> </ul>   |  |
|                   | <ul> <li>Update of archaeological method statement (AMS), and implementation of archaeological</li> </ul>      |  |
|                   | method statements and exhumation management plan.  |  |
|                   | <ul> <li>Road use changes and closures at Randle Street and nearby streets east of Central Station.</li> </ul> |  |
|                   | Cumulative impacts from contemporaneous projects   |  |
|                   | Bounce Hotel strip out and demolition.   |  |
|                   | <ul> <li>Station Design and Precinct Plan development and submission.</li> </ul>                               |  |
|                   | Development of the Heritage Interpretation Plan.   |  |
|                   | <ul> <li>Update to Heritage Register for Northern Concourse deconstruction and heritage asset</li> </ul>       |  |
|                   | recovery.  |  |
|                   | Hazardous materials removal to the Eastern Suburbs Rail Concourse and within ghost                             |  |
|                   | platforms.   |  |
| SMEW              | Early investigations.  |  |
| SIVIL VV          | Pre commencement approval documentation reviews.   |  |
|                   | Approval of low impact OOHW under the OOHW Protocol.   |  |
| Line Wide         | Planning for early investigations.   |  |
| LITTE WILLE       |  |  |
|                   | Strategy for delivery or maniple approvation   |  |
|                   | <ul> <li>Input to pre commencement approval documentation.</li> </ul>  |  |