

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Healthy Buildings International Pty LtdA.C.N. 003 270 693A.B.N. 39 003 270 693

Erica van den Honert Director Infrastructure Management Department of Planning, Industry and Environment GPO Box 39 SYDNEY NSW 2001 7 November 2019 Ref: 170108-ER-DPIE-Oct19-SSJ CS NCW LW S2B

Dear Erica

Re: Sydney Metro City & South West - ER Monthly Report for October 2019 – CS, NCW, SSJ, LW and S2B

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications (MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), MOD3_ Martin Place Metro Station (22 March 2018), MOD5_Blues Point Acoustic Shed (2 November 2018) and MOD6_ Administrative Changes (21 February 2019);
- Condition A26(j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI_8256 Approval (12 December 2018).

The attached summary details the following key activities undertaken by ERs for Sydney Metro – City and South West Chatswood to Sydenham (C2S) during the month of **October 2019** for Sydenham Station Junction, Central Station, Northern Corridor and Line Wide Works.

It also provides a summary in relation to the Sydney Metro - Sydenham to Bankstown (S2B) for the same period.

Yours sincerely

Jo Robertson Environmental Representative

Sydney Metro Cc: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam Koutsamanis, Margarita Ognjanovic, Andrew Hendy, Simon Fisher, Tim Solomon DPIE Cc: Elizabeth Williamson, Rob Sherry, Alice Pryke IEP Cc: Larry Weiss, Julie Dickson

Summary of Contra	ict Packages	Environmental Representative/s
Sydenham Station Junction (SSJ)		Jo Robertson (Jo Heltborg – observer)
Central Station		Michael Woolley
Northern Corridor (NCW)		Peter Hatton
Line Wide (Tallawong to Bankstown)		Peter Hatton
Sydenham to Bankstown Sydney Metro Early Works (SMEW)		Jo Robertson
Key Construction A		
Sydenham Station Junction (SSJ)	 Retaining wall construction in the rail corworks area. The CSR works area is also be corridor. Rail Corridor - Construction of footings ar (ULX) connections. Preparation for track in Burrows Ave/ Bolton Street - Lift shafts in lifted by crane during the Christmas shute 11 Sydenham Rd Marrickville - Excavation bore is continuing. Excavation of treated stockpiled and treated potential acid sulp tanks are available for use as required on Sydenham Pumping Station - Constructio the aqueduct support columns and heads culvert cells planned to be lifted on top o Sieving of recovered cemetery sands is or Archaeological investigation at up-ramp t commenced. Works for the installation for permanent Excavation of natural soils beneath Metro offsite disposal. Water misters were in us Piling, excavation within hoardings on the the new canopy, is ongoing. This has bee on how to reduce noise in the area; and h Trains personnel. A portion of the Olympic Tunnel has beer Station using an extended bridge, aided b Hoardings and signage for wayfinding on commuters to access the Station safely see Services investigation and formwork instas short term "igloo" enclosure constructed 	a for the culvert is ongoing. Construction of under d potential acid sulphate soil (PASS) has resulted in shate soil. Concrete washout facilities and sediment site. In of the new access ramp continues. Construction of stocks is ongoing in Sydenham Pit. Super T's and <u>f pylons</u> . Ingoing. With the trachyte steps and other heritage items o design level has commenced for a future piling to Platform 16 for CSR works phase B has water treatment plant have commenced. D Box track slab. Loading of spoil onto trucks for i.e. e Concourse, for the installation of foundations for in noisy work and has been the subject of discussions how to reduce exposure to the noise of Sydney in closed. As a consequence, commuters enter Central by additional wayfinding signage. the upper Concourse have been installed to allow
Northern Corridor	 Metro Box excavation south of Devonshir 	
Works (NCW)	There were no inspections conducted by ER ir	
Line Wide	 Excavation for and of the Fire Ring Main, 	
		es, CSR installation and backfilling of trenches. wiring (OHW) footings.
SMEW		IRX) works were completed with all disturbed areas

	 Recent work to remove a large tree at Ness Avenue. 	
	 Canterbury compound area being established in the corridor adjacent to Charles Street. 	
50.1	 Removal of a large tree in Zone 13 that required power outage due to high voltage overheads. 	
ER Inspections	There were three importions and stad by the FD in October 2010, larger identified during	
SSJ	There were three inspections conducted by the ER in October 2019. Issues identified during inspections involved: management of bulldust, reinstatement of minor visual screening, classification of stockpiled materials, and tree protection at laydown compounds.	
Central Station	There were three ER inspections conducted in October 2019. It was noted that the water treatment plant has been commissioned and made operational. Key issues identified were related to surface water management.	
NCW	There was no ER inspection conducted in October 2019.	
Line Wide	There were two inspections in October 2019. The key issues discussed at these inspections were: public information signage, use of incorrect beeper on an excavator, and dust management. It was also noted that the site has a high standard of general housekeeping.	
SMEW	There was one ER inspection conducted in October 2019. JHLOR discussed the potential installation of a silt berm as an end of line control given the proximity of works to the River. The ER requested additional information on the construction methodology to better understand the proposed works in this area. Installation of silt controls and the preservation of ground cover should be undertaken in the immediate future.	
Endorsed Docume	nt/s	
SSJ	■ Nil	
Central Station	■ Nil	
NCW	■ Nil	
Line Wide	 Out of hours works (OOHW) Application 005 WE 12 SMTF Rev 00 	
SMEW	 OOHW Application: General site-wide minor works – September/October and WE19, Rev 05: 21 October 2019. OOHW Application prepared for Metron T2M for invasive investigation activities to be undertaken during Weekend 19 possession (9/11/19-10/11/19) Rev 00: 18 October 2019 	
Non-compliance/	Incidents or Repeat Complaints	
Sydney Metro has complaint have be	been providing summaries of complaints to DPIE daily and a summary to the ER. Responses to each en noted in each complaint report, with follow up actions often defined in revised reports. Key or te are discussed below for the respective projects.	
SSJ	Complaint aspects for this site during the period included: parking (subsequently found to be not project related, dust suppression and vibration for tamping (since found to be from Sydney Trains activities). There were no incidents for SSJ reported to the ER under conditions A41 to A44 of SSI 7400.	
NCW	Complaint aspects for this site during the period included: Oversize parking and parking generally, the sound levels of vehicle reversing beepers, noise from OOHW, and vibration There were no incidents were reported to the ER under conditions A41 to A44 of SSI 7400.	
Central Station	Complaint aspects for this site during the period included: Key complaint for his period were associated with noise due to concrete breaking works at Northern Concourse , and water on the floor in the Southern Baggage Pedestrian Tunnel with the water reported o be coming from the metro box excavation. There were no incidents for Central reported to the ER under conditions A41 to A44 of SSI 7400.	
Line Wide	There was a complaint about a lack of notification about night work in the area related to the Central to Waterloo 33kv work. It was since discovered that the property was included in recent door knocks and reminder notification. There were no incidents were reported to the ER under conditions A41 to A44 of SSI 7400.	
SMEW	There were no incidents reported to the ER under conditions A36 of SSI 8256.	
Audits		
SSJ	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
NCW	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
Central Station	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
SMEW	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	

Line Wide	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
Looking Forward	- Core Focus Areas	
Sydney Metro	Compliance review for Q3 for 2019	
SSJ	 Upcoming possession work, negotiation of EPL for upcoming construction works (possession shut down). Culvert work, and completion of supporting structures, and associated impacts. 	
NCW	 Nil 	
Central Station	 Station Precinct Design Plan Investigations and approvals associated with the use of the Eveleigh Facility 	
Line Wide	 SMTF (North) construction site works Central to Waterloo 33 Kv works Cumulative impacts from adjacent projects 	
SMEW	 Temporary road closure works (Various) Erosion and sediment control and associated retaining wall works between Campsie and Canterbury Stations Approval of OOHW under the OOHW Protocol Works conducted during possession under the Sydney Trains Environment Protection Licence (EPL) 	