

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Healthy Buildings International Pty LtdA.C.N. 003 270 693A.B.N. 39 003 270 693

Erica van den Honert Director Infrastructure Management Department of Planning, Industry and Environment GPO Box 39 SYDNEY NSW 2001 11 October 2019 Ref: 170108-ER-DPIE-Sep19-SSJ CS NCW LW S2B

Dear Erica

Re: Sydney Metro City & South West - ER Monthly Report for September 2019 – CS, NCW, SSJ, LW and S2B

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications (MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), MOD3_ Martin Place Metro Station (22 March 2018), MOD5_Blues Point Acoustic Shed (2 November 2018) and MOD6_ Administrative Changes (21 February 2019);
- Condition A26(j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI_8256 Approval (12 December 2018).

The attached summary details the following key activities undertaken by ERs for Sydney Metro – City and South West Chatswood to Sydenham (C2S) during the month of **September 2019** for Sydenham Station Junction, Central Station, Northern Corridor and Line Wide Works.

It also provides a summary in relation to the Sydney Metro - Sydenham to Bankstown (S2B) for the same period.

Yours sincerely

Jo Robertson Environmental Representative

Sydney Metro Cc: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam Koutsamanis, Margarita Ognjanovic, Andrew Hendy, Simon Fisher, Tim Solomon DPIE Cc: Elizabeth Williamson, Rob Sherry, Alice Pryke IEP Cc: Larry Weiss, Julie Dickson

Summary of Contract Packages		Environmental Representative/s	
Sydenham Station Junction (SSJ)		Alberto Paludetto	
Central Station		Alberto Paludetto	
Northern Corridor (NCW)		Peter Hatton	
Line Wide (Tallawong to Bankstown)		Peter Hatton	
Sydenham to Banks (SMEW)	stown Sydney Metro Early Works	Jo Robertson	
Key Construction A			
Sydenham Station Junction (SSJ) Central Station	 ongoing Burrows Ave - Installation of services, win 11 Sydenham Rd Marrickville - VENM has Potential Acid Sulfate Soil (PASS) has been Sydenham Pumping Station - Construction aqueduct support columns ongoing in Syden Track slab construction at the northern end the space beneath the slab is ongoing Excavation between Devonshire Street Tu Stockpiling of excavated sand in portable continuing for mechanical and hand sievin Trimming and detailing of piles is ongoing South of Devonshire St Tunnel the cappin Lead contaminated material removal. Co The wheel wash in operation The use of sprays for dust suppression is one 	been imported to raise the site to working level in treated and will undergo analysis and classification in of new access ramp continues. Construction of denham Pit. and of the Metro Box is ongoing. Deep excavation of unnel and Y tunnels in Metro Box in ongoing bins from the former Devonshire Street Cemetery is ing g beam construction to support track slab is ongoing vered waste awaiting removal after classification ongoing	
	 Piling and excavation within hoardings on the Concourse for the installation of foundations for the new canopy is ongoing 		
Northern Corridor Works (NCW)	 Artarmon Station to the termination of th Signal support and construction Stockpile management and remo Import of material Combined services route (CSR) a 	works oval	
Line Wide	 Site compound establishment and construction controls 	uction / implementation of erosion and sediment	
SMEW		enue: Under Road Crossing (URX) - The majority of ve been completed. Some minor reinstatement of	
ER Inspections			
SSJ	There were two inspections conducted by the ER in September 2019. Issues identified during inspections involved ensuring concrete collection points are available and reinforcing use thereof. Hand held hoses are installed at 11 Sydenham Rd to assist dust suppression. Effectiveness of dust suppression measures for the Pit should be monitored as the weather gets hotter.		
Central Station	There were two ER inspections conducted in September 2019. It was noted that the water treatment plant has been commissioned and made operational. Key issues identified were related to surface water management.		
NCW	There was one ER inspection conducted in Se controls onto Brand Street from the south recently constructed acoustic barrier at west	eptember 2019. It was noted that sediment run-off have been effective however the effectiveness of ern end of Hopetoun Avenue may be compromised ssues identified during inspections included on-going	
Line Wide	There were two inspections in September 201	.9. The key issues discussed at these inspections d the interface with the operational metro facility.	

SMEW	There were two ER inspections conducted in September 2019. Limited issue identified due to the	
	limited scale of work. Planning for works near the Cooks River is ongoing. The ER requested	
	additional information on the construction methodology to better understand the proposed	
	works in this area.	
Endorsed Docume	ent/s	
SSJ	 Consistency Assessment (SSJ-PACA-008) Turnout Build Area 	
Central Station	■ Nil	
NCW	 Out of hours works application (OOHWA) #30 Week 11 Week Ending (WE) 12 Sept 2019 Rev02 (Portion 7A + 7B) 	
Line Wide	 Artarmon/Willoughby Bulk power Supply Early Works Investigation/Survey 	
	 Surry Hills / Waterloo Bulk Power Supply - Early Works Services Investigation/Survey OOHWA 	
	005	
	 OOHWA 003 WE 12 SMTF Rev00 	
	 OOHWA 003 WE 12 SMTF Rev01 	
	 OOHWA 003 WE 12 SMTF Rev02 	
SMEW	 OOHW Albermarle Street URX Rev 01 	
	 Utility Management Strategy Rev 5 	
Non-compliance/	Incidents or Repeat Complaints	
Sydney Metro has	been providing summaries of complaints to DPIE daily and a summary to the ER. Responses to each	
complaint have be	en noted in each complaint report, with follow up actions often defined in revised reports. Key or	
repeat items of no	te are discussed below for the respective projects.	
SSJ	Complaint aspects for this site during the period included: Storage of rail tracks alongside haul	
	road access near business, heavy truck movements, parking, and behaviour of workers.	
	There were no incidents for SSJ reported to the ER under conditions A41 to A44 of SSI 7400.	
NCW	Complaint aspects for this site during the period included: Oversize parking and parking generally,	
	the sound levels of vehicle reversing beepers, noise from OOHW, and vibration	
	There were no incidents for NCW reported to the ER under conditions A41 to A44 of SSI 7400.	
Central Station	Complaint aspects for this site during the period included: Dust property access delays, workers	
	behaviour, safety and pedestrian access. There were no incidents for Central reported to the ER	
	under conditions A41 to A44 of SSI 7400.	
Line Wide	No incidents, non compliances or complaints.	
SMEW	Complaints included concerns about consultation and construction impacts. There were no	
	incidents reported to the ER under conditions A36 of SSI 8256.	
Audits		
SSJ	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
NCW	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
Central Station	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
SMEW	No ER involvement in audit activity including Independent Environmental Audits (IEA program).	
Line Wide	Registration with TeamBinder for Line Wide (Auditor query)	
Looking Forward -		
Sydney Metro	 Compliance review for Q3 for 2019 	
SSJ	 Flood management and the flood report compliance 	
	 Protection and relocation of sewer and water utilities 	
	Communications relocation works	
NCW	 Management of noise and vibration during possession works in light of numerous complaints 	
	 Management of sediment movement and mud-tracking off-site 	
	Management of project vehicle parking	
Central Station	 Development of the Heritage Interpretation Plan 	
	 Development of the Station Precinct Design Plan 	

Line Wide	 Planning for early investigations including BPS routes from Campsie to Canterbury, Surry Hills to Waterloo and Artarmon to Willoughby Strategy for delivery of multiple approvals Endorsement of early works and OOHW applications Input and endorsement as required to pre commencement approval documentation Occupation of SMTF (North) construction site and commencement of erection of site buildings, construction of car park/laydown area and construction of ERSED works including a new sediment treatment pond
SMEW	 Cumulative impacts from adjacent projects Temporary road closure works (Various) Erosion and sediment control between Campsie and Canterbury Stations Approval of OOHW under the OOHW Protocol Works conducted during possession under the Sydney Trains Environment Protection Licence (EPL)