



MONTHLY NOISE AND VIBRATION REPORT CITY & SOUTHWEST ACOUSTICS ADVISOR

Project:	Chatswood to Sydenham SSI-7400		
For period:	August 2022	Authorisation:	
Prepared by:	Daniel Weston		Destro
Date of issue:	7 September 2022		

Introduction

EMM Consulting Pty Limited (EMM) presents the August 2022 AA Noise and Vibration Report for the Sydney Metro City and Southwest project as required by SSI 15_7400 A27 (g) vi.

A reference table for the acronyms used in this report is provided on the last page.

Acoustic Advisor Activity

- Review and/or endorsement of:
 - Barangaroo Noise and Vibration Monitoring Report September 21 to March 22 Rev 0 (review only);
 - o CSM Construction Noise and Vibration Management Plan Rev 13 (review only);
 - LWW Waterloo Cable Pulling CNVIS Rev 4; and
 - WISD Construction Noise and Vibration Management Plan Rev 3.
- Review and endorsement of out of hours work applications (OOHWA) and extensions for:
 - Barangaroo OOHWA10 Escalator Delivery Rev 0;
 - LWW OOHWA236 Surry Hills BPS Randle Lane HV Cabling Rev 0 and Rev 1;
 - o LWW OOHWA239 Waterloo Cable Pulling Rev 0;
 - MPISD OOHWA96 North Site Ausgrid connection works Rev 1;
 - MPISD OOHWA95 North Site hoarding works Rev 1;
 - PSISD OOHW41 Footpath works Rev 3;
 - o PSISD OOHW43 Rev 6;
 - o PSISD OOHW44 Crane Installation Rev 5; and
 - WISD OOHW42 Rev 3.
- Attendance at Sydney Metro and DPE monthly meeting, and ongoing meetings with CNISD, VCISD, Barangaroo Station, PSISD, MPISD, CSM and WISD contractors.

Inspections, audits and site visits

The following was done:

- CNISD inspection with ER on 19 August 2022; and
- CSM inspection with ER on 24 August 2022.

Monitoring status

 Real-time noise and vibration monitoring (with real-time access) is ongoing at CNISD, VCISD Barangaroo, PSISD (noise only), MPISD and CSM. The WISD Contractor is operating real-time noise monitors to assist with site noise management. This is not a requirement of their CNVMP and is optional only. We have access to this data on an as-needs basis only (eg when complaints are received).

Noise and vibration complaints

- Complaints from Chatswood (x2), Crows Nest (x6), Barangaroo (x4) and Waterloo (x2) were received:
 - the complaints at Chatswood and Waterloo were caused by approved OOH works and classified as unavoidable;
 - the complaints at Crows Nest were caused by standard construction hours demolition of the Hume Street Bridge using excavators with hydraulic hammers. All complaints were from commercial receivers in relation to noise and vibration from the works. Follow up actions from the contractor included detailed community consultation and noise and vibration measurements by the contractor's acoustics consultant. We are yet to see the noise and vibration monitoring report, however we are reasonably satisfied with the contractor's response based on the evidence seen to date. These works are now complete.
 - the four complaints at Barangaroo were from one resident about a range of matters including OOH noise during the recent Hickson Road steel beam removal and escalator delivery which required an ROL and therefore out of hours work. We are reasonably satisfied with the contractor's response which included ongoing consultation with the resident and noise measurements at a location representative of the complainant's house. These works are now complete.

Initiatives

Attended noise monitoring records are requested by EMM on a regular basis to verify that the
appropriate level of information is being recorded by noise monitoring personnel and overall
adherence to CNVMP and NMP requirements.

Non-compliances, incidents and events

Nil.

Ongoing and upcoming environmental risks

- At Barangaroo, there is continued detailed demolition of structure below Hickson Road and of a
 capping beam using hydraulic hammers fitted to excavators. The contractor has explored
 alternate methods such as the use of pulverisers, however hydraulic hammers were required due
 to site constraints. We have reinforced with the contractor the requirement to consider alternate
 methods to hydraulic hammers and will continue to monitor this during future demolition scope.
- OOH works, particularly long running concrete pours and/or oversize deliveries at ISD sites at WISD, PSISD, VCISD and CNISD will continue.
- A significant phase of utilities works will continue at PSISD and WISD. OOHW is required due to ROL requirements and footpath permits from Council.
- Capping beam removal will continue at WISD during standard construction hours. The alternative lower noise method of wire saw and core drilling (consistent with successful removal of capping beam at PSISD) is being used where feasible and has proved to provide additional benefits in terms of dust suppression and smaller exclusion zones on site.
- Most ISDs are now approaching or are at/above ground level with noise levels increasing and
 works being more visible to the community and nearest noise-sensitive receivers. This increases
 the risk of noise impacts and complaints and will be monitored closely.

• Public domain works will be starting at Crows Nest in the coming months. This will require a substantial scope of utilities works of which some will be required OOH to facilitate utility service provider requirements.

Recommendations (incl auditing):

Nil

Acronyms

CNISD	Crows Nest Integrated Station Development	
CNVIS	Construction Noise and Vibration Impact Statement	
CNVMP	Construction Noise and Vibration Management Plan	
CSM	Central Station Metro	
DPE	NSW Department of Planning and Environment	
ER	Environmental Representative	
ISD	Integrated Station Development	
LWW	Line Wide Works	
MPISD	Martin Place Integrated Station Development	
NVA	Noise and Vibration Assessment	
NVMP	Noise and Vibration Monitoring Plan	
оон	Out of hours	
оонш	Out of hours work	
OOHWA	Out of Hours Work Application	
OSOM	Oversize, overmass	
PSISD	Pitt Street Integrated Station Development	
ROL	Road Occupancy License	
SSJ	Sydenham Station Junction	
TSS	Traction Substation	
VCISD	Victoria Cross Integrated Station Development	
WISD	Waterloo Integrated Station Development	